

Nunavut Water Board  
P.O. Box 119  
Gjoa Haven, Nunavut  
X0B 1J0

18 November 2019

Attention: Manager of Licencing

**RE: 8BC-DYE1929, Culvert Replacement DYE-M**

On 28-Feb-2017, the Nunavut Water Board offered guidance on the replacement of culverts at the North Warning System site, DYE-M located at Cape Dyer in Nunavut (letter attached). This work was completed from 16-Aug-2019 to 07-Sep-2019.

As required by water licence 8BC-DYE1929 Item G3, attached are two sets of drawings:

1. Design drawings, stamped by an engineer; and
2. As built drawings, marked up by Kudlik Construction Ltd. – the company that implemented the work on-site.

Please contact me with any questions,

  
William Wyman  
Environmental Services Officer,  
Raytheon Canada Limited, North Warning System  
Email: [William.wyman@raytheon.com](mailto:William.wyman@raytheon.com)  
Phone: 613-787-3655

Attachments:

- NWB Guidance Letter: 170228 3BC-DYE0919 Guidance Letter for Onsite Culvert Work-OCEE;
- Project Design Drawings: EP-1535-FDDwg REV1 Repair Roadway at DYE-M - Sealed (15.F.20); and
- Project As-built Drawings: EP-1535 DYE-M Roadway Repair as built drawings