



P.O. Box 119
Gjoa Haven, NU X0B 1J0
Tel: (867) 360-6338
Fax: (867) 360-6369

ᓇᓱᑦ ሀᓂᓱᑦ ንᓂጀᕗ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI
OFFICE DES EAUX DU NUNAVUT

File: 8BW-CLY0810/TR/B,1

September 29, 2010

Mr. Harry Flaherty, Project Director
Qikiqtaaluk Corporation
P.O. Box 1228
Iqaluit, NU
X0A 0H0

Email: hflaherty@qcorp.ca

Subject: Licence 8BW-CLY0810 – Part B Item 1 - Review of 2009 Annual Report

Dear Mr. Flaherty;

On March 30, 2010, the Nunavut Water Board (NWB or Board) received the document entitled “Road Between the Hamlet of Clyde River and Cape Christian Annual Report 2009 Season”, dated March 2010 (2009 Annual Report) from the Qikiqtaaluk Corporation (Licensee) as required by Part B Item 1 of water licence 8BW-CLY0810 (Licence). The NWB distributed the 2009 Annual Report to interested parties for information purposes on April 7, 2010. No comments were received.

The NWB has reviewed the 2009 Annual Report and notes the following for the Licensee's consideration:

- Part B Item 1 (e) of the Licence requires the Licensee to provide a summary of all information requested and results of the Monitoring Program as part of its annual report. The Monitoring Program includes Part J Item 3 of the Licence requiring the Licensee to determine the GPS coordinates of locations where wastes associated with construction and operation are deposited. The Board notes that the 2009 annual report does not provide GPS coordinates. The Licensee is advised to provide this information as part of its 2010 annual report.
- Part B Item 1 (e) of the Licence requires the Licensee to provide a summary of all information requested and results of the Monitoring Program as part of its annual report. The Monitoring Program includes Part J Item 4 of the Licence requiring the Licensee to conduct basic water quality testing that includes pH, temperature, conductivity, total suspended solids, and total oil and grease, upstream and downstream of the Clyde River bridge construction site prior to, weekly during construction and upon completion. The

Board notes that the 2009 annual report does not provide temperature results and does not provide any monitoring results during construction of the Clyde River Bridge. If this information is available, the Licensee is advised to provide it as part of its 2010 annual report.

Should you have any questions regarding annual reporting requirements or otherwise, please do not hesitate to contact the NWB office.

Yours truly,

Original signed by:

Phyllis Beaulieu (for)
David Hohnstein, C.E.T.
Director Technical Services

DH/tla/pb

c.c. Qikiqtani Distribution List