

# **Inspection Report**

License #: 3BC-NET0913 - Canadian Wildlife Service - Nikku Island Goose Tagging Project

Inspector: A. Keim

**CIDMS # 389968** 

Client	Canadian Wildlife Service – Environment Canada		
Mailing Address	Suite 150, 123 Main Street Winnipeg, Manitoba Canada R3C 4W2		
Inspection site location	Nikku Island, Nettling lake, Nunavut.		
Contact name	Jim Leafloor	Title	Biologist
Last inspection date	August 15th, 2008		
Inspection start date	July 25, 2009		
Region	Qikiqtani		



INAC, Nunavut District P.O. Box 100 Building 918 Iqaluit, NU, XOA 0H0

Submitted Via E-Mail

Our File: 3BC-NET0913

Your File:\_

CIDM # 389968

February 15, 2010

Jim Leafloor Canadian Wildlife Service Environment Canada Protected Areas and Stewardship Unit Suite 150, 123 Main Street Winnipeg, Manitoba Canada R3C 4W2

## RE: Water License Inspection CWS Bird Banding Project - Nikku Island Camp July 25, 2009

The following inspection report is generated on the information collected during a compliance inspection carried out on the Nikko Island Camp located at Latitude: 66° 35' 54"N Longitude: 71° 30' 91"W in the Qikiqtani Region. The inspection was conducted to determine compliance with the terms and conditions of the Water License (3BC-NET0913) issued to Canadian Wildlife Service Environment Canada by the Nunavut Water Board (NWB).

The report references the applicable parts of the Water License (3BC-NET0913) and the findings observed under each of those parts. During the writing of this report a compliance review was undertaken of the documents, plans and manuals filed by the Licensee and located on the Nunavut Water Board's FTP site.

It is to be noted that a representative of the Canadian Wildlife Service was not present during the inspection.

#### Issues noted in previous Inspections;

- Camp was previously unlicensed.
- Camp did not have an incinerator installed but were practicing Open Burning in barrels on site.
- Historic waste and garbage remains on site.
- No secondary containment was present on site.
- Fuel belonging to outside agents was present in the cache of fuel.
- Water usage was not recorded.

#### During the period of the 2009 inspection the following issues were identified by the Inspector;

- An incinerator was not present on site.
- None of the required work to consolidate waste and garbage on site had been undertaken by the licensee.
- No secondary containment was noted on site.

It is noted that the Camp was not occupied at the time of the Inspection

#### Affaires indiennes et du Nord Canada

Non-Compliance: Issues identified during the July 25<sup>th</sup> 2009 inspection and/or review of relevant material

#### Issues with a known or anticipated human health impacts;

Open burning of wastes containing hazardous materials was noted at the on site. ( Paint cans and oil cans noted within the Burn barrel)

### Issues where there is a known or anticipated environmental impairment;

- Historic bulk wastes are not segregated and progressive reclamation work does not appear to be on-going.
- An incinerator was not noted on site.

#### Issues where there is a known or suspected violation of a requirement of the Water License or Act;

- o A License was recently issued to the Canadian Wildlife Service. The items noted above may be addressed in the submission of the 2009 annual report due by March 31<sup>st</sup> 2010.
- o The above will be reviewed at that time.

Andrew Keim	
Inspector's Name	Inspector's Signature

Cc:

Peter Kusugak - Manager Field Operations Section- Indian and Northern Affairs Canada Phyllis Beaulieu - Manager licensing - Nunavut Water Board















