

WATER LICENCE INSPECTION FORM

⊠ Original ☐ Follow-Up Report

Action Required

Licensee Licensee Represen				entative						
Combustion Performance			Gabriel Choquette							
Licence No. / Expiry			Representative's Title							
8wlw-WAG1920			Business owner							
Land / Other Authorizations			Land / Other Authorizations							
3AM-IQA1626										
Date of Inspection Inspector										
October 13, 2020 Jonathan MESHER										
Activities Inspected										
☐ Camp ☐ Drilling ☐ Roads/Hauling ☐ Other:		☐ Mining ☐ Construction ☐ Other:		Reclamation Fuel		Storage				
Conditions: A - Acceptable C - Concern U - Unacceptable NA – Not Applicable NI – Not Inspected					ected					
Water Use	Condition	Comment	Site Conditions		Condit ion	Comme nt	Haz/Mat Manager	ment	Condition	Comment
Intake/Screen	Α		Water Manager	ment Structures	NA		Storage		NA	
Flow Measure. Device	NA		Culverts / Bridg	es	NA		Spills		NA	
Source:	NA		Drainage		NA		Spill Plan		NI	
Water Use:	NA		Erosion / Sedim	ent	NA					
Recirculation (y /n)	NA		Mitigation Mea	sures	Α		Administrative			
			Reclamation Ac	tivities	NA		Records		NI	
			Materials Stora	ge	NA		Reports		NI	
Waste Disposal			Signage				Plans		NI	
Waste Water	NA						Notifications		Α	
Solid Waste	NA		Monitoring				Other			
Hazardous Waste	NA		Sample Collection	on / Analysis	Α		Follow-up from		NI	
							previous inspectio	n		
*The number in the comments field will correspond with specific comments provided below.										
Samples taken by Inspector:		Location(s):								
☐ Yes ⊠ No										

Background

Comments

SECTION 1

The licensee is currently operating Wash and Go project in the City of Iqaluit, this licensee uses two types of pumps/ water storage tanks to operate this business. On June 30th, 2020 the inspector noted the licensee withdrawing water from a location adjacent to the north forty landfill (see photo 1 for pumping location), at that time the inspector questioned the licensee about the approved withdrawal location. The licensee informed me that they are approved to withdrawal from that waterbody but down stream of that location, due to a diversion upstream the majority of the water body bypasses the location at north forty. The inspector requested that the licensee withdrawal from only the locations approved in the authorization issued by the NWB.

Non-Compliance with Act or Licence

Inspection

- During the inspection the licensee was no longer using water.
- Both pumps used for this activity has Fish mesh screens. See photo 3 for fish screen.
- Upon review of the approved water usage and the water usage logs (see photos 3 for water usage logs) it appears that on June 12 and July 13th, 2020 the licensee used 10,000L more than approved by the NWB. The inspector is requesting that if the licensee wishes to utilize the larger tank identified in photo 4 below that, the licensee seek approval for this quantity of water or limit the daily with drawl rate to 2000L per day and gradually fill the tank.
- No further concerns were noted at the tie of the inspection.



Comments

- No.	Crown-Indigenous Relations
	and Northern Affairs Canada

SECTION 2

Non-Compliance with Act or Licence

Action Required

1. The licensee is to only withdrawal from locations approved by the NWB.

2.Due to the over usages of water, the inspector is requesting that the licensee amend their license to allow for such usage or limit daily usage to the approved quantity.

Inspector's Name	
Jonathan MESHER	
Signature	
Date	
October 7, 2020	

Water Resource Officer, Nunavut Region

Crown Indigenous Relations and Northern Affairs Canada – CIRNAC

Jonathan.mesher@canada.ca


Office #: 867-975-4296 Fax: 867 979-6445

Date	Camera	Inspector	Authorization
Photo Log	Sony Cyber-shot	J.Mesher	8WLW-WAG
Photo 1			
		64	
14			
Description: Water withdra	wal form unapproved area	STATE OF THE STATE OF THE STATE OF	

Date	Camera	Inspector	Authorization
	Sony Cyber-shot	J.Mesher	8WLW-WAG
Photo Log			
Photo 2			







Description: water usage log

