# 2BE-PEL0813 Inspection August 11, 2012
# Photos

## Amaruk Airstrip

Figure 2. Salt Bags at the airstrip.

Figure 1. Oil pails at the airstrip.

## Amaruk Camp

Figure 3. Helipad area; assorted barrels visible.  Spill kits present.

Figure 4. Berm collapsed.



Figure 5. Full barrels, no containment.

Figure 6. Berms present but full of water.

Figure 7. Incinerator barrel - berm full in low corner.

Figure 8. Incinerator Barrel - hole cut for hose.

Figure 9. Barrel stand - hose has come off. Berm full of water.

Figure 10. Sheen on water of same stand.

Figure 11. Oils stacked outside without containment.

Figure 12. Salts stacked outside without containment.

**Figure 13. Door of this building was open. Jerry cans and oils present.**

Figure 15. Left side of shed with antifreeze and Rain-X visible.




Figure 14. Right side of shed with oil pails and jerry can visible.

Figure 17. Open barrel with scrap and waste visible.

Figure 16. Garbage barrel (with a lid) outside of kitchen tent with garbage still present.

## Drill Sites

Figure 18. 15 W 0586176 / 7575766 - timbers and debris.

Figure 19. AMKPB-11

## Fuel Cache Sites



Figure 20. Qavvik cache.  Ashes, waste, and barrel imprints visible.

Figure 21. Charred debris left at Qavvik.

Figure 22. New Tuktu cache.  Ashes, core boxes, and barrel imprints visible.

Figure 23. Some of the garbage visible at New Tuktu.

**Figure 24. Arnak cache.  Wood and ashes visible.**