



NWB Tools

Megan Porter <megan.porter@nwb-oen.ca>

[Licensing] FW: Polaris Inspection Schedule Clarification

slines@tlaconsultants.ca <slines@tlaconsultants.ca>

Mon, Nov 3, 2014 at 5:15 PM

To: david.hohnstein@nwb-oen.ca, Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>, Robin Ikkutisluk <robin.ikkutisluk@nwb-oen.ca>, Sean Joseph <sean.joseph@nwb-oen.ca>, Sonia Aredees <sonia.aredes@nwb-oen.ca>

Cc: bruce.donald@teck.com, Ian Parsons <Ian.Parsons@aandc-aadnc.gc.ca>, Andrea Morgan <Andrea.Morgan@aandc-aadnc.gc.ca>

Hi Dave, Phyllis, Robin,

As per my email earlier today regarding the update on Polaris, you will find a link below to the correct version of the 2014 Geotechnical Inspection Report.

The document that was accidentally provided to the NWB on October 17, which is on the NWB ftp site, is in fact a draft. Please note that AANDC received the correct version on October 14 and brought to Teck's attention the issue of the two different reports for clarification, which we discussed with AANDC today by telephone.

Golder has provided the attached memo clarifying the difference between the draft and final, and you can download the correct (final) version from the link below.

Please replace the draft version currently on the ftp site with the correct version.

Our apologies for the mix up. If you have any questions please contact myself or Bruce.

Kind regards,

Steve

Stephen Lines P.Biol., M.Sc.

T: 514-604-4459

E: slines@tlaconsultants.ca



From: Johnson, Darrin [mailto:Darrin_Johnson@golder.com]
Sent: November 3, 2014 6:32 PM
To: 'Donald Bruce KIMB'
Cc: slines@tlaconsultants.ca; Merry, Peter
Subject: Polaris Inspection Schedule Clarification

Bruce,

Please find attached to this email a letter clarifying the recommended Polaris geotechnical inspection schedule. Also please find below a link that can be used to download the final 2014 Polaris geotechnical inspection report.

File(s) will be available for download until **03 December 2014**:

File: [1408454_Final 2014 Polaris Geotechnical Inspection Report_09OCT2014.pdf](#), 25,913.33 KB

Attachment link(s) within this email have been sent via Golder Associates Secure File Transfer (SFT). To retrieve the attachment(s), please click on the link(s).

Golder Help Desk - North America: [+1 \(877\) 246 5337](tel:+18772465337) | Australia/New Zealand/Asia: [+61 \(3\) 8862 3588](tel:+61388623588) | Europe: [+44 \(0\) 844 484 3060](tel:+4408444843060) | Africa: [+27 \(11\) 2544832](tel:+27112544832) | South America: +56 (2) 616-2222 (Chile) +51 (1) 610 1702 (Peru) | Worldwide: +1 (403) 299 5603 | helpdesk@golder.com

Accellion File Transfer

[Accellion File Transfer](#)

Regards,

Darrin

Darrin Johnson (M.Sc., P.Eng. (ON,BC,YK,NWT,NU), PMP) | Associate - Senior Geotechnical Engineer | **Golder Associates Ltd.**

6925 Century Avenue, Suite #100, Mississauga, Ontario, Canada L5N 7K2

T: [+1 \(905\) 567 4444](tel:+19055674444) | **D:** [+1 \(905\) 567-6100 x2521](tel:+19055676100) | **F:** [+1 \(905\) 567 6561](tel:+19055676561) | **C:** [+1 \(647\) 261-9108](tel:+16472619108) | **E:** darjohnson@golder.com | **www.golder.com**

Work Safe, Home Safe

This email transmission is confidential and may contain proprietary information for the exclusive use of the intended recipient. Any use, distribution or copying of this transmission, other than by the intended recipient, is strictly prohibited. If you are not the intended recipient, please notify the sender and delete all copies. Electronic media is susceptible to unauthorized modification, deterioration, and incompatibility. Accordingly, the electronic media version of any work product may not be relied upon.

Golder, Golder Associates and the GA globe design are trademarks of Golder Associates Corporation.

Please consider the environment before printing this email.



1408454_Polaris Inspection Schedule Clarification Letter_03NOV2014.pdf

76K