



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
FAX: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᓂᓕᓂᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI

File No: NWB1CUL0207

April 13, 2004

Attention: Vernon Betts
Western Canada Environment Manager
Barrick Gold Corporation
Suite 700, 1055 W. Georgia Street
Vancouver, BC
Email: vbetts@barrick.com

Re: Assignment of Licence NWB1CUL0207 (Type B)

Dear Mr. Betts:

We have reviewed your October 16, 2003 application to the Nunavut Water Board ("NWB" or "Board") to transfer Licence NWB1CUL0207 from Homestake Canada Incorporated ("HCI") to Barrick Gold Corporation ("BGC"). This application was deemed to be an application for assignment pursuant to section 44 of the *Nunavut Waters and Nunavut Surface Rights Tribunal Act* ("Act").

The Board gave public notice of your application for assignment (name change) and invited interested parties to provide comments. The Department of Indian and Northern Affairs (DIAND) informed the Board that it did not have concerns with respect to the proposed assignment. No other submissions were made.

On balance, the Board is satisfied that the operation of the appurtenant undertaking by the prospective assignee will not be likely to result in a contravention of any condition of the licence or any provision of the Act or the regulations. Therefore, in accordance with section 44(2) of the Act, the Board hereby authorizes the assignment of water license NWB1CUL0207 from HCI to BGC, effective on the date of this letter, which will be placed in the NWB Public Registry.

The Board would like to take the opportunity to highlight the following matters that will require immediate action by BGC:

Financial Security (Licence NWB1CUL0207, Part B, Item 1)

Under the terms of Licence NWB1CUL0207 (Part B, Item 1), **the Licensee shall post and maintain a security in the amount of \$50,000.00 dollars** in the form and schedule as required by the Minister of Indian and Northern Affairs Canada. Please contact Ms. Elizabeth Sherlock,

A/Manager, Water Resources, DIAND, at (867) 975-4550 regarding DIAND's requirements to meet this licence condition.

Annual Assessment of Current Mine Restoration Liability (Licence NWB1CUL0207, Part F, Item 2)

Under the terms of Licence NWB1CUL0207 (Part F, Item 2), the Licensee shall provide "a revised status report and implementation schedule to reflect the current status of reclamation and monitoring. The status report shall include a detailed cost estimate of the remaining work required until final restoration" if this information has not been recently submitted as Part of BGC's Annual report, **the Board hereby notifies BGC** that the status report shall be submitted to the Board for review and approval within six (6) months of this letter.

Spill Contingency Plan (Licence NWB1CUL0207, Part E, Item 3)

Under Part E, Item 3, the Licensee is required to submit, for approval, a Spill Contingency Plan, which shall be modified annually as necessary to reflect changes in operations. As this assignment will likely involve changes in operations, personnel and site facilities, the current Spill Contingency Plan shall be reviewed and updated.

The Board hereby notifies BGC that it shall submit to the Board for approval, within one month of the effective date of this assignment, a revised Spill Contingency Plan.

Abandonment and Restoration Plan (Licence NWB1CUL0207, Part F, Item 4)

Part F, Item 4 of Licence NWB1CUL0207 requires the Licensee to submit, for approval, a revised Abandonment and Restoration Plan, which shall be modified annually as necessary to reflect changes in operations. As this assignment may involve changes in operations and abandonment and reclamation activities, the current Abandonment and Restoration Plan shall be reviewed and updated.

The Board hereby notifies BGC that it shall submit to the Board for approval, within six months of the effective date of this assignment, a revised Abandonment and Restoration Plan.

Enforcement

Effective the date of this letter, **Licence NWB1CUL0207 is assigned to BGC, and all terms and conditions of this licence remain in effect.** Provisions for the enforcement of this water licence assigned by the NWB pursuant to the Act are found in sections 85 to 94 of the same Act, which gives the Minister of Indian and Northern Affairs Canada the power to designate inspectors and analysts responsible for inspection and compliance. We ask you to contact the Inspector at the DIAND District Office in Iqaluit to obtain a copy of any enforcement documents related to this license.

Please contact me at your convenience should you have questions about this assignment. You may also contact Dionne Filiatrault, NWB's Manager of Technical Services, regarding any technical matter pertaining to this licence.

Sincerely,

A handwritten signature in dark ink, appearing to read 'P. di Pizzo', with a stylized flourish at the end.

Philippe di Pizzo
Executive Director

Attachment: Licence

cc. Distribution List