

Environmental Working Group Summary of Recommendations

Site: CAM-2 (Gladman Point)

Date: February 26, 2009

Report: *"The Collection of Landfill Monitoring Data at the CAM-2 Gladman Point Site – 2008 FINAL Report"*, prepared by AECOM Canada Ltd.

Recommendations:

(please refer to the Teleconference Meeting Minutes for further explanation of these recommendations)

General:

1. In last year's monitoring report (2007), the overall landfill performance for the Tier II Soil Disposal Facility and for the Non-Hazardous Waste Landfill were both rated as Marginal, mainly because of an extensive number of new tension cracks. The EWG agreed with this rating.

In this year's (2008) monitoring report, both landfills are still rated as Marginal (*i.e.*, implying that their performance appears to be deteriorating with time) despite the fact that the landfills seem to be stable compared to last year's conditions and that no new tension cracks have been identified. Therefore, the EWG believes that an overall landfill performance of Acceptable for both landfills would be more appropriate

Respectfully Submitted,



David Harding, M.Sc. P.Eng.

On behalf of the Environmental Working Group

Ref: CAM-2 Recommendations-February 09.doc