

2014-12-17 Transmission via email

Mr. Geoffroy Lécureur, ing. Principal Directeur – Iqaluit Projet 2700 Jean-Perrin, local 350 Québec (Québec) G2C 1S9

T: 418 527-5643

Email: glecureur@sintra.ca Ref. No.: RQ14-214-4

Re: Clarification on Disposal of Tank from the Drum Cache

Mr. Lécureur,

The purpose of this letter is to respond to the question about the disposal of the tank from the drum cache. Authorisation was sought from the City of Iqaluit to dispose of the tank in their landfill. They accepted to dispose of the tank with the condition that the tank be cleaned and cut up prior to being brought to the landfill. This was done to the satisfaction of the receiver at the landfill. You will find attached the confirmation from the city that they would dispose of the tank in their landfill. You will also find attached the receipt from the City of Iqaluit Landfill for the disposal of the tank.

Should you have any additional questions please do not hesitate to contact me.

Sincerely,

Greg Johnson

Project Director

Email: gjohnson@qenv.ca Tel: 514-940-3332 x 150 Fax: 514-940-3435

Attch: Email confirmation (1 pg) and receipt (1pg) from the City of Igaluit

Cc: Jacques Dion, Sylvain Laberge – Qikiqtaaluk Environmental Inc.

Patrice Richard, Michel Boulianne – Sintra Inc.

Greg Johnson

From: Jeff MacMunn [j.macmunn@city.iqaluit.nu.ca]

Sent: April 15 2014 11:28
To: gjohnson@qenv.ca
Subject: RE: Steel Reservoir

Yes we will take it as long as it is cleaned out and crushed or cut up.

Jeff MacMunn

7<10 P

Landfill Foreman

 4°

City of Iqaluit

ᠫᠳᢗ᠆ᠺᡔ᠘᠙᠙᠙᠘᠙

j.macmunn@city.iqaluit.nu.ca

Phone# 867-979-5640 Cell# 867-222-2946

From: Greg Johnson [mailto:gjohnson@qenv.ca]

Sent: Tuesday, April 15, 2014 10:45 AM

To: <u>i.macmunn@city.iqaluit.nu.ca</u>

Subject: Steel Reservoir

Good morning Jeff,

I just wanted to follow up on our conversation last week about the steel reservoir that we would like to dispose of at the landfill. Can you please confirm that you will accept the reservoir for disposal at the landfill, as long as any residue has been cleaned off the inside and outside of the tank, and it has been crushed or cutup to reduce the volume as much as possible?

Thank you,

Greg Johnson, M.Sc.A., P.Eng. Project Director



Iqaluit & Montreal

Toll Free: 1-866-634-6367 x 150 Tel: (514) 940-3332 x 150 Cell: (514) 717-7604

www.genv.ca

善

Pensez vert, est-ce nécessaire d'imprimer ce message? Think green, is it really necessary to print this message?

Iqaluit

CITY OF IQALUIT SOLID WASTE FACILITY

RECEIPT OF SERVICE RECEIPT NUMBER 051531

20cd20	
DATE July 24 /14 TIME /	.30 AM ATTENDANT DMI
NAME &C	PHONE NO 9-5400
ADDRESS BOX 1228	
VEHICLE TYPE Dunptraik	LICENCE NO.
WASTE TYPE Fill	VOLUME 10n3x2
INSPECTION TYPE Mastal	
1500-0° + 20% - \$600	
FEEDRIVER'S SIGNATURE	
The last section of the la	CUSTOMER