

P.O. Box 119 GJOA HAVEN, NU X0B 1J0 TEL: (867) 360-6338 Fax: (867) 360-6369 ລ໑° ΔL፫ሊትና ቴበLትዣ NUNAVUT IMALIRIYIN KATIMAYINGI NUNAVUT WATER BOARD OFFICE DES EAUX DU NUNAVUT

May 11, 2011 File No: 1BR-ROB0813/TR/B1

Natalie Plato Director, Contaminated Sites Program Indian and Northern Affairs Canada PO Box 2200 Iqaluit, NU XOA 0H0

E-mail: natalie.plato@inac-ainc.gc.ca

<u>Subject: Submission of 2010 Annual Report – 1BR-ROB0813</u>

Dear Ms. Plato:

The Nunavut Water Board ("NWB") acknowledges receipt, on May 5, 2011, of the 2010 Annual Report from Indian and Northern Affairs Canada, as a requirement of Part B, Item 1 of 1BR-ROB0813. Included with the annual report are the following additional documents:

- Appendix 1 Executive Summary in English and Inuktitut
- Appendix 2 Summary of 2010 Remediation Program, NWB Licence Reporting Requirements, 2010 Surface Water Monitoring Report
- Appendix 3 Long Term Monitoring Report
- Completion Report for Roberts Bay and Ida Bay Mine Sites Site Remediation Program, Nunavut

The submission has been placed on the NWB public registry and is available from the NWB ftp site username: public, password: registry. This report is forwarded to the distribution list for information only. Anyone wishing to provide comments may do so by return e-mail to licensingadmin@nunavutwaterboard.org

Sincerely,

Original signed by:

Richard Dwyer Licensing Administrator

cc. Kitikmeot Distribution List