



Ministère de l'Environnement

☎ 867.975.5924
☎ 867.975.5981

- 7) Samples and pictures should be taken before and after the abandonment and reclamation of the project area.

Spill Contingency Plan:

- 1) Kennecott Exploration Canada must provide contact names, addresses, and a 24 hr phone number for the persons in charge for activating the spill contingency plan. Also, the names, addresses and phone numbers of the owners and project manager should be included into the plan.
- 2) The proponent should provide a site map making certain to include all infrastructure, fuel storage facilities, and locations of spill kits. This map should also include UTM coordinates for the project areas and spill kits for fast response in the event of a large spill.
- 3) Quantities and MSDS sheets for all fuels and chemicals should be provided in the plan for workers safety and for spill response. The plan should also include clean up and disposal options for contaminated soils.
- 4) The proponent needs to provide the workers with adequate training for spill response and clean up.
- 5) Kennecott should provide locations and contents of the spill kits. This would ensure that each kit contains enough materials for the workers to respond to minor spills.

We thank the NWB for giving us the opportunity to review the abandonment & restoration plan and Spill Contingency Plan. Please contact me if you have any further questions or comments.

Sincerely,

Original signed by

Ian Rumbolt
Coordinator of Land Use
Department of Environment
C/O Environmental Protection
Government of Nunavut
Box 1000, Stn. 1360
Iqaluit, NU, X0A 0H0
Phone: (867) 975-5924
Fax: (867) 975-5981
Email: irumbolt@gov.nu.ca