

Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

[Licensing] 2BE-MSX0712 Inspection of August 16 2014

1 message

Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>

Mon, Dec 1, 2014 at 1:26 PM

To: Licensing Department < licensing@nwb-oen.ca>, rlehari@silvermet.ca

Cc: Baba Pedersen <Baba.Pedersen@aandc-aadnc.gc.ca>, Erik Allain <Erik.Allain@aandc-aadnc.gc.ca>, karen.kharatyan@nwb-oen.ca

Hello Mr. Lehari,

Please find attached a report of an inspection conducted for the above water licence in August. Several deficiencies remain on this expired licence; restoration work that should have been completed prior to the licence expiry is still outstanding. It is noted that AANDC Inspector Baba Pedersen conducted an inspection of this project (LUP# N2007J0012) in 2013, and required that remedial work be completed in 2014. This work was still not completed at the time of my inspection.

It is further noted that while Silvermet applied for and received a burn permit from the NWB in 2012, there was flagrant disregard for the conditions of that permit.

These deficiencies are to be addressed early in the snow-free season in 2015 (see dates included in the attached report) and a follow-up report with photos submitted to myself and RMO Pedersen to show that the work has been completed. Failure to do so will result in enforcement measures.


Regards,

Eva Paul

Water Resources Officer | Agent des ressources en eau Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada Nunavut Regional Office | Bureau régional du Nunavut Building 969, PO Box 2200 | Édifice 969, CP 2200 | Iqaluit, NU XOA 0H0

Phone | Tél. : 867-975-4548 Cell | Mobile: 867-222-6490 Fax | Téléc. : 867-979-6445 Eva.Paul@aandc-aadnc.gc.ca

2 attachments



2BE-MSX0712 Photos of August 16 2014 Inspection.pdf 3202K