

P.O. Box 119 GJOA HAVEN, NU X0B 1J0 TEL: (867) 360-6338 FAX: (867) 360-6369 אבת הלי האבי האבי האבי אינו אינו שמדבר BOARD NUNAVUT IMALIRIYIN KATIMAYIT OFFICE DES EAUX DU NUNAVUT

File No.: 2BE-TOR1014/TR/B2

April 16, 2012

Mr. Gordon Clarke Vice President, Exploration North Arrow Minerals Inc. Suite 860, 625 Howe Street Vancouver, BC V6C 2T6

Email: gord@northarrowminerals.com

Subject: Licence No. 2BE-TOR1014 "Torp Lake Project" Kitikmeot Region,

Nunavut; Submission of 2010-2011 Annual Report

Dear Mr. Clarke;

The Nunavut Water Board ("NWB" or "Board") reviewed the 2010-2011 Annual Report for the above mentioned project, which was submitted on February 27, 2012. The Report was distributed for information.

The Annual Report indicates that no work has been undertaken in the project area since the licence was issued. Therefore no water has been used and no waste generated to date.

The Licensee is reminded that in accordance with Part H, Item 1 of the licence, the NWB requires the submission of an addendum to the approved spill contingency plan 30 days following licence issuance. NWB was not in receipt of the spill plan addendum.

Should you have any questions, please feel free to contact the undersigned at (867) 360-6338 Ext. 30 or <a href="k.kharatyan@nunavutwaterboard.org">k.kharatyan@nunavutwaterboard.org</a>, at your earliest convenience.

Yours truly,

Karén Kharatyan Technical Advisor

cc: Distribution List – Kitikmeot