

- 1) The licensee is to ensure all hazardous material is kept within secondary containment.
 - Hazardous material that is awaiting backhaul will be stored within secondary containment prior to loading it onto the plane. Sabina will utilize the bulk fuel storage containment berm, instaberms, or construct a hazardous waste management berm to store the material.
- 2) The licensee is to ensure no waste/water resulting from washing vehicles is enter water and/or causing erosion.
 - Washing vehicles in advance of routine/scheduled maintenance will only occur in lined, contained washbays. Any contaminated water will be captured and managed as per the terms and conditions of the water licence.
- 3) The inspector is recommending that licensee install drip trays below the fuel tank noted in a, III.
 - A drip tray has been installed under the fuel drum. In addition, Sabina has placed an order at the MLA for the same 45-gallon drum yellow housing units utilized at Goose Lake that completely enclose the fuel drum.