

**From:** [Rykaart, Maritz](#)  
**To:** ["Bob Princewright"](#)  
**Cc:** [Calvin G](#); [Kevin Mather](#); [Doug Fieldings](#); [Jerry Graham](#); [Ishan Fechter](#); [Greg Blaylock](#); [Bay, Hope](#); [Wade, Lowell](#); [Miskolczi, Iozsef](#); [Mcgregor, Murray](#); [Church, Simon](#); [Miller, Megan](#)  
**Subject:** Pollution Control Pond Repair  
**Date:** Wednesday, June 08, 2011 9:55:45 AM  
**Attachments:** [image001.gif](#)  
[PollutionControlPLLiner\\_Memo\\_1CH008.033\\_emr\\_20110608.pdf](#)

---

Bob

As discussed please find attached SRK's recommendations for correcting the liner installation in the pollution control pond. We trust that you will pass this along to the contractor.

Please do not hesitate to contact me if you have any questions.

Regards

Maritz

**Maritz Rykaart** *Ph.D., P.Eng.*

Principal Consultant



SRK Consulting (Canada) Inc.

Suite 2200, 1066 West Hastings Street, Vancouver, V6E 3X2, Canada

**Tel:** +1-604-681-4196; **Fax:** +1-604-687-5532

**Mobile:** + 604-928-1552; **Direct:** +1-604-601-8426

**Email:** [mrykaart@srk.com](mailto:mrykaart@srk.com)

[www.srk.com](http://www.srk.com)

*This transmission is intended for the sole use of the addressee, and may contain information that by its privileged and confidential nature is exempt from disclosure under applicable law. You are hereby notified that any dissemination, distribution or duplication of this transmission by someone other than the intended recipient or its designated agent is strictly prohibited. If you have received this transmission in error, please notify the sender immediately by replying to this transmission, or by collect call to the above phone number.*

 Please consider the environment before printing this e-mail.