

Appendix E Reconciliation of SRK and Water License Thermistor Station ID's

Station ID		Northing	Easting	Thermistor String Serial Number	Status	Location	Area	Comments	Data Logger/ Thermistor Reader
Water License 2AM-DOH0713	SRK								
n/a	SRK-11	7559117.00	434347.00	00577-2	Inactive	North Dam	Doris Mining Area	Replaced by NI1 to NI24 series	Omega 866C
n/a	SRK-13	7559171.72	434383.32		Inactive	North Dam	Doris Mining Area	Replaced by NI1 to NI24 series	Omega 866C
n/a	SRK-14	7559059.45	434291.66	690007	Active	Near North Dam	Doris Mining Area	Baseline data	Omega 866C
n/a	SRK-15	7559171.62	434383.00	690012	Inactive	North Dam	Doris Mining Area	Replaced by NI1 to NI24 series	Omega 866C
n/a	SRK-16	7559092.00	434323.20	0577-3	Inactive	North Dam	Doris Mining Area	Replaced by NI1 to NI24 series	Omega 866C
T4	SRK-19	7563211.92	432983.69	690006	Inactive	Beach Laydown Area	Roberts Bay	Baseline data - Destroyed during construction	Omega 866C
T5	SRK-20	7563129.78	432986.02	690009	Inactive	Beach Laydown Area	Roberts Bay	Baseline data - Destroyed during construction	Omega 866C
T8	SRK-22	7562026.69	432971.94	690003	Active	East of Doris Airstrip	Roberts Bay	Baseline data	Omega 866C
T7	SRK-23	7561665.77	432901.86	690008	Inactive	South Apron Doris Airstrip	Roberts Bay	Baseline data - Destroyed during construction	Omega 866C
n/a	SRK-24	7559493.64	432344.49	690001	Active	Near crusher at Q2	Doris Mining Area	Baseline data	Omega 866C
DOR-5	SRK-26	7558819.91	433422.37	690002	Inactive	Junction Doris Rd and Tail Lk Road	Doris Mining Area	Baseline data - Destroyed during construction	Omega 866C
DOR-1	SRK-28	7559046.27	433043.30	690011	Inactive	Camp Pad	Doris Mining Area	Baseline data - Destroyed during construction	Omega 866C
SI2	SRK-32	7555914.51	435554.73	690010	Inactive (Repairs needed)	South Dam Area	Doris Mining Area	Baseline data - No Longer Functioning. Could be repaired.	Omega 866C
SI3	SRK-33	7555930.36	435613.59	690005	Active	South Dam Area	Doris Mining Area	Baseline data	Omega 866C
SI4	SRK-34A	7555941.61	435640.69	690004	Inactive	South Dam Area	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
T1	SRK10-DCB2 Doris Bridge East	7559478.35	434036.99	690000	Active	Doris Creek Bridge Abutment East	Doris Mining Area	Doris Water License	TH2016
T2	SRK10-DCB1 Doris Bridge West	7559475.15	434067.76		Active	Doris Creek Bridge Abutment West	Doris Mining Area	Doris Water License	TH2016
n/a	SRK-35	7559477.53	434035.64	690013	Inactive	Doris Creek - West	Doris Mining Area	Baseline data: Replaced by T1	Omega 866C
n/a	SRK-37	7559090.54	434328.97	690013	Inactive	North Dam	Doris Mining Area	Replaced by NI1 to NI24 series	Omega 866C
n/a	SRK-38	7558254.33	434525.84	TS0015	Active	Tail Lake West Side	Doris Mining Area	Baseline data	Omega 866C
n/a	SRK-39	7556391.33	435164.13	TS0011	Active	Tail Lake West Side	Doris Mining Area	Baseline data - Top bead not functioning	Omega 866C
n/a	SRK-40	7558546.86	435492.39	TS0014	Inactive	Tail Lake East Side	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
n/a	SRK-41	7559129.11	434358.55	TS0012	Inactive	North Dam Area	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
n/a	SRK-42	7559081.34	434402.62	TS0013	Inactive	North Dam Area	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
SI5	SRK-43	7555923.82	435584.52	TS0010	Inactive	South Dam Area	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
n/a	SRK-50	7559177.00	433807.00	TS1618	Active (Repairs Needed)	Doris Lake North End	Doris Mining Area	Baseline data - Malfunctioning (readings suspect/incorrect)	Omega 866C
n/a	SRK-51	7559165.54	434390.70	TS2048	Inactive	North Dam Area	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
n/a	SRK-52	7559082.73	434316.33	TS2047	Inactive	North Dam Area	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
SRK-53	SRK-53	7556906.93	435184.24	TS1625	Inactive	Tail Lake West Side	Doris Mining Area	Baseline data-No longer functioning in 2014	Omega 866C
SRK-54	SRK-54	7556467.00	435632.00	TS1626	Inactive	Tail Lake East Side	Doris Mining Area	Baseline data - Surrounded by Water - No longer functioning	Omega 866C
SRK-56	SRK-55	7557813.27	434935.95	TS1621	Inactive	Tail Lake West Side	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
SRK-56	SRK-56	7558258.00	435334.00	TS1621	Inactive	Tail Lake East Side	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
SRK-57	SRK-57	7557812.13	434937.72	TS1623	Active	Tail Lake West Side	Doris Mining Area	Baseline data	Omega 866C
SRK-58	SRK-58	7557704.54	435284.89	TS1622	Inactive (Repairs Needed)	Tail Lake East Side	Doris Mining Area	Baseline data - No longer functioning (could be repaired?)	Omega 866C

Station ID		Northing	Easting	Thermistor String Serial Number	Status	Location	Area	Comments	Data Logger/ Thermistor Reader
Water License 2AM-DOH0713	SRK								
n/a	SRK-62	7558994.93	434500.74	TS2046	Inactive	Tail Lake North End	Doris Mining Area	Baseline data - No longer functioning	Omega 866C
T1	SRK-JT1-09	7563297.00	432534.00	TS2667	Active	Jetty	Roberts Bay Jetty	Doris Water License - Bottom bead not functioning	TH2016
T2	SRK-JT2-09	7563264.00	432550.00	TS2668	Inactive	Jetty	Roberts Bay Jetty	Replaced with SRK-JT2-12	TH2016
T2	SRK-JT2-12	7563264.00	432550.00	TS2668	Inactive	Jetty	Roberts Bay Jetty	Doris Water License - No Longer Functioning	TH2016
n/a	08SBD380	7504780.24	441079.71		Unknown	South of Boston Camp	Boston Mining Area	Baseline data - Boston Water License	ELA0036 & VW2106
n/a	08SBD381A	7504813.94	441070.40		Unknown	South of Boston Camp	Boston Mining Area	Baseline data - Boston Water License	ELA0036 & VW2106
n/a	08SBD382	7505140.53	441025.86		Unknown	South of Boston Camp	Boston Mining Area	Baseline data - Boston Water License	ELA0036 & VW2106
n/a	08PMD669	7550955.12	433300.23		Unknown	between Patch and Windy Lakes	Madrid Mining Area	Baseline data - Windy Water License	ELA0036 & VW2106
n/a	08PSD144	7548989.92	435177.97		Unknown	Patch Lake Island	Madrid Mining Area	Baseline data - Windy Water License	ELA0036 & VW2106
n/a	08TDD632	7559369.75	433915.20		Inactive	West Side Doris Lake N	Doris Mining Area	Baseline data - No longer functioning (July 2013)	ELA0036 & VW2106
n/a	08TDD633	7557646.05	433402.21		Inactive	West Side Doris Lake	Doris Mining Area	Baseline data - No longer functioning - Never read / no data	ELA0036 & VW2106
n/a	SRK-12-GTC-DH01	7558917.20	433169.18		Active	Pollution Control Pond	Doris Mining Area	Doris Water License	TH2016
n/a	SRK-12-GTC-DH02	7558912.96	433225.25		Active	Pollution Control Pond	Doris Mining Area	Doris Water License	TH2016
n/a	SRK-12-GTC-DH03	7558930.81	433225.25		Active	Pollution Control Pond	Doris Mining Area	Doris Water License	TH2016
DOR-6	SRK10-DWB1	7555673.50	432703.40		Active	Doris-Windy Road Bridge #2	Madrid Mining Area	Doris Water License	TH2016
DOR-7	SRK10-DWB2	7555644.40	432708.20		Active	Doris-Windy Road Bridge #2 / #3	Madrid Mining Area	Doris Water License	TH2016
DOR-8	SRK10-DWB3	755615.00	432712.80		Active	Doris-Windy Road Bridge #3	Madrid Mining Area	Doris Water License	TH2016
DOR-9	SRK10-DWB4	7554860.30	432444.00		Active	Doris-Windy Road Bridge #4	Madrid Mining Area	Doris Water License	TH2016
DOR-10	SRK10-DWB5	7554831.30	732437.00		Active	Doris-Windy Road Bridge #4	Madrid Mining Area	Doris Water License	TH2016
NI1	ND-HTS-040-31.5	7559100.71	434324.01		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI2	ND-HTS-040-33.5	7559100.71	434324.01		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI3	ND-VTS-040-KT	7559100.71	434324.01		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI4	ND-VTS-060-DS	7559115.28	434337.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI5	ND-HTS-060-33.5	7559115.28	434337.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI6	ND-HTS-060-31.0	7559115.28	434337.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI7	ND-HTS-060-28.8	7559115.28	434337.72		Active	North Dam	Doris Mining Area	Water License. One bead not working.	Campbell Scientific Data Logger
NI8	ND-VTS-060-KT	7559115.28	434337.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI9	ND-VTS-060-US	7559106.54	434346.46		Inactive	North Dam	Doris Mining Area	Damaged during construction, location of damage unknown	Campbell Scientific Data Logger
NI10	ND-VTS-085-DS	7559133.96	434353.91		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger

Station ID		Northing	Easting	Thermistor String Serial Number	Status	Location	Area	Comments	Data Logger/ Thermistor Reader
Water License 2AM-DOH0713	SRK								
NI11	ND-HTS-085-25.3	7559133.96	434353.91		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI12	ND-HTS-085-29.4	7559133.96	434353.91		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI13	ND-HTS-085-33.5	7559133.96	434353.91		Inactive	North Dam	Doris Mining Area	Cut during construction, end could not be found to be spliced.	Campbell Scientific Data Logger
NI14	ND-VTS-085-KT	7559133.96	434353.91		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI15	ND-VTS-085-US	7559125.08	434363.23		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI16	ND-VTS-130-DS	7559167.23	434384.47		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI17	ND-HTS-130-28.8	7559167.23	434384.47		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI18	ND-HTS-130-31.0	7559167.23	434384.47		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI19	ND-HTS-130-33.5	7559167.23	434384.47		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI20	ND-VTS-130-KT	7559167.23	434384.47		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI21	ND-VTS-130-US	7559158.49	434393.93		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI22	ND-HTS-175-32.5	7559200.63	434414.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI23	ND-HTS-175.33.5	7559200.63	434414.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger
NI24	ND-VTS-175-KT	7559200.63	434414.72		Active	North Dam	Doris Mining Area	Doris Water License	Campbell Scientific Data Logger

Legend:

	Thermistor Cable: Inactive Not Repairable
	Thermistor Cable: Inactive Repairs Needed
	Thermistor Cable: Unknown Condition
	Thermistor Cable: Active