

P.O. Box 119 GJOA HAVEN, NU X0B 1J0 TEL: (867) 360-6338

Fax: (867) 360-6338

ລ**ວ**° ΔL~ሊት' ቴ∩**L**ት℃ NUNAVUT IMALIRIYIN KATIMAYINGI NUNAVUT WATER BOARD OFFICE DES EAUX DU NUNAVUT

July 20, 2011 File No: 2AM-JER0410/TR/A3

Pamela Strand, P. Geol. President and CEO Shear Diamonds (Nunavut) Corp. Suite 220, 17010 – 103 Avenue Edmonton, AB T5S 1K7

E-mail: pstrand@shearminerals.com

Subject: <u>Submission of Response to June 2011 Inspection Report of the Jericho Diamond Mine Property, 2AM-JER0410</u>

Dear Ms. Strand:

The Nunavut Water Board ("NWB") acknowledges receipt of a submission from Shear Diamonds (Nunavut) Corp. entitled Response to June 2011 Inspection Report of the Jericho Diamond Mine Property for Water Licence 2AM-JER0410 received on July 12, 2011 as a requirement of Part A, Item 3 of water license 2AM-JER0410. This submission has been placed on the NWB public registry and is available from the NWB ftp site username: public, password: registry.

Please be advised that this is the revised response letter that properly reflects the proper licence number – note that there is an error in Ian's inspection report and that the licence number is not 0411 but 0410.

This report is forwarded to the distribution list for information only. Anyone wishing to provide comments may do so by return e-mail to licensing@nunavutwaterboard.org

Sincerely,

Original signed by:

Phyllis Beaulieu Manager of Licensing

Cc: Kitikmeot Distribution List