



NWB Tools

Ida Porter <ida.porter@nwb-oen.ca>

[Licensing] Recent events at Lupin Mine (2AM-LUP0914, amended)

Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>

Tue, Aug 11, 2015 at 2:46 PM

To: Karyn Lewis <klewis@elginmining.com>, Patrick Downey <pdowney@elginmining.com>

Cc: Erik Allain <Erik.Allain@aandc-aadnc.gc.ca>, Terry Sewell <Terry.Sewell@aandc-aadnc.gc.ca>, "Cavanagh Norm" <Norm.Cavanagh@justice.gc.ca> <Norm.Cavanagh@justice.gc.ca>, Christine Kowbel <ckowbel@lawsonlundell.com>, "licensing@nwb-oen.ca" <licensing@nwb-oen.ca>

Hello Karyn,

I acknowledge receipt of the August 6, 2015 letter from Mr. Tong of SRK Consulting (Canada) Inc. in relation to condition (a) of the Inspector's Direction dated July 22, 2015.

As described in Mr. Tong's letter, material has been added to the dam but the compaction and riprap placement has not yet taken place. Mr. Tong indicates that the observed freeboard was approximately 0.5 m at the time of inspection and that discharge is ongoing. No specific dates with respect to the completion of the required work are suggested in the report or your e-mail below.

Please provide the anticipated dates whereby the compaction/riprap work and the decant will be completed.

Regards,

Eva Paul

Water Resources Officer | Agent des ressources en eau

Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada

Nunavut Regional Office | Bureau régional du Nunavut

Building 969, PO Box 2200 | Édifice 969, CP 2200

Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548

Cell | Mobile: 867-222-6490

Fax | Téléc. : 867-979-6445

Eva.Paul@aandc-aadnc.gc.ca

>>> Karyn Lewis <klewis@elginmining.com> 8/10/2015 10:24 PM >>>

[Quoted text hidden]