


## REFERENCES

- BGC Engineering Inc. 2000. Thermistor Installation Program, Dam 1A, Dam 2, M Dam, Cell 1 and Esker, Lupin Mine, Nunavut. Report submitted to Echo Bay Mines Ltd., Project No. 0256-002-01, December 11, 2000, 7 pages plus figures and appendices.
- BGC Engineering Inc. 2003. Dam 6 Site Investigation and Raise Design, Lupin Mine, Nunavut. Report submitted to Kinross Gold Corporation, Project No. 0256-006, July 25, 2003, 31 pages plus figures and appendices.
- Geocon Inc. 1982. As-Built Tailings Containment Area, Lupin Project. Report submitted to Echo Bay Mines Ltd., Project No. A1207/01186-3, December 15, 1982, 26 pages plus figures and appendices.
- Golder Associates Ltd. 1992. 1992 Perimeter Dam Construction Drawings. Issued for tender to Echo Bay Mines Ltd., February 1992, 4 sheets.
- Golder Associates Ltd. 2004. 2004 Dam Safety Review, Perimeter Tailings Dams, Lupin Mine, Nunavut. Report submitted to Kinross Gold Corporation, Project No. 04-1321-022, December 2004, 36 pages plus figures and appendix.

## FIGURES



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	As shown	DESIGNED:	JWC
DATE:	OCTOBER 2006	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT:



**BGC Engineering Inc.**

AN APPLIED EARTH SCIENCES COMPANY

**BGC**

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT	ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE	LUPIN MINE LOCATION MAP		
PROJECT No.	0256-012-01	FIGURE No.	1
		REV.	