From: Andrew Keim

To: "licensingadmin@nunavutwaterboard.org"; "spills@gov.nt.ca"; Mercer, Jeff; Pratt, Jeffrey; Robertson, Kevin;

rharmer@gov.nu.ca

Cc: <u>Girard, Dominique</u>; <u>Grondin, Louise</u>; <u>Robert, Stephane</u>

Subject: Re: 777\_Ruptured\_Line October 11, 2011

Date: Sunday, October 16, 2011 12:43:42 PM

Attachments: <u>ATT00013.png</u>

## Jeffrey,

Could you please provide the following in follow up;

- a. The location of the contaminated soils storage.
- b. Volume of soils removed
- c. Location of absorbent pads
- d. a reason for the delay in reporting

Many thanks

Andrew Keim Water Resources Officer INAC Nunavut Regional Office P.O. Box 100

Iqaluit, Nunavut X0A 0H0

\*NEW Email: \* Andrew.Keim@aandc-aadnc.gc.ca

Phone: (867) 975-4289 Fax: (867) 979-6445

>>> Jeffrey Pratt <jeffrey.pratt@agnico-eagle.com> 10/14/2011 7:05 PM >>>

Hello,

Attached is a spill report depicting the incident which occurred October 11, 2011 at Agnico-Eagle Mines Ltd. Meadowbank site.

This spill is being reported as required by the conditions under the Nunavut Water Board Licence 2AM-MEA0815, Part H, item 9 b pursuant to subsection 12(3) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act. Also;

This spill is being reported as required by Environment Canada's Storage Tank Systems For Petroleum Products and Allied Petroleum Products Regulations section 41 pursuant to paragraph 212(1)(a) of the Canadian Environmental Protection Act, 1999. Also;

This spill is being reported as required by the Government of Nunavut's, Environmental protection Act paragraph 5.1(a).

If you require further information don't hesitate to contact me.

Jeffrey Pratt Environmental Coordinator

## Agnico-Eagle Mines Ltd. Meadowbank Division

Phone: 819-759-3555 ext: 6728 jeffrey.pratt@agnico-eagle.com

