



Canada NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130 FAX: (867) 873-6924 EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

_	REPORT DATE: MONTH - DAY	-YE	/EAR REPORT TIME											
Α	04-01-2018		ŀ	14:30				C) ORIGINAL SPILL REPORT, OR		REPORT NUMBER				
_	OCCURRENCE DATE: MONTH			OCCURRENCE TIME]οι	JPDATE #						
В	03-31-2018		16:00				TO THE ORIGINAL SPILL REPORT							
\sim	· '	PERMIT NUMBER (IF APPLICABLE)						WATER LICENCE NUMBER			APPLICABLE)			
С	KIOL-BL-14						N/	NB-2A	M-1525	5				
D	GEOGRAPHIC PLACE NAME O			IRECTION FROM I	NAMED LO	OCATION	N REGION DINWT MININAVUT DIADJACENT JURISDICTION OR OCEAN							
	MEADOWBANK I										OR OCEAN			
Е	LATITUDE		UTES 05		ns 00			GITUDE	16			١0	- 20	
_	DEGREES 65 RESPONSIBLE PARTY OR VE		02001100				BIGE LOCATI	ION	MINTO I EQ	90 ,	SECONDS 32			
F	AGNICO EAGLE		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0											
	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION											
G														
	PRODUCT SPILLED				OUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES U.N. NUMBER									
	Coolant			379	379 liters						N/A			
Н	SECOND PRODUCT SPILLED	(IF AF	PPLICABLE)	QUANT	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRE					ES	S U.N. NUMBER			
1	SPILL SOURCE Haul Truck			SPILL CAUSE				-1.7				AREA OF CONTAMINATION IN SQUARE METRES		
			Mechanical issue RECOVERY DESCRIBE ANY ASSISTANCE REQUIRED AMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISK							12 m2				
J	FACTORS AFFECTING SPILL (DESCR	DESCRIBE ANY ASSISTANCE REQUIRED						HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT					
_	ADDITIONAL INFORMATION O	N, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS												
	, , , , , , , , , , , , , , , , , , , ,													
	A bearing from the radiator fan has broken. The fan hit the radiator and punctured it. The radiator has emptied from his content. The operator called a mechanic department to repair it.													
	There were no off-site impacts or discharge to any receiving watercourses. The distance to the													
1/	closest lake is 600 m													
K	Contaminated material was brought in the tailing.													
	Spill Location: Northing; 65°05'00.3" Easting: 96° 00'32.3" on IOL													
	Contact Information: Martin Archambault (819) 759-3555 Ext 6744													
					•	•								
	REPORTED TO SPILL LINE BY POSITION				la			1						
	i i		POSITION Sr Coord				EMPLOYER Agnico Eagle Mines				LOCATION CALLING FROM Meadowbank		TELEPHONE 8197593555	
_	ANY ALTERNATE CONTACT POSITION			EMPL						ALTERNATE CONTACT		ALTERNATE TELEPHON		
M	Nancy D-Harvey Superintenda			tendant							Meadowbank		8677934510	
REPORT LINE USE ONLY														
N 1	RECEIVED AT SPILL LINE BY POSITION				EMPLO						OCATION CALLED		REPORT LINE NUMBER	
N	STATION OPERATOR			RATOR	1					YEL	YELLOWKNIFE, NT		(867) 920-8130	
LEA	AGENCY DEC DCCG DC	□ INAC □ NEB	DINEB DTC SIGNIFIC			FICANCE - MINOR - MAJOR					US OPEN CLOSE			
AGE	AGENCY CONTACT NAME										REMARKS			
				ne e paravella			CONTACT TIME				Control 1152			
LEAD AGENCY										_				
FIRS	T SUPPORT AGENCY	SUPPORT AGENCY												
SEC	OND SUPPORT AGENCY													
THIE	ID SUPPORT AGENCY													