



---

## 2AM-MEL1631 Culvert 6 & 21 Design Report

---

**Sara Savoie** <sara.savoie@agnicoeagle.com>

Mon, May 11, 2020 at 8:33 AM

To: Richard Dwyer <richard.dwyer@nwb-oen.ca>

Cc: Sergey Kuflevskiy <sergey.kuflevskiy@nwb-oen.ca>, licensing <licensing@nwb-oen.ca>, Meliadine Environment Supervisors <meli.environment.supervisors@agnicoeagle.com>

Good morning Mr. Dwyer,

Agnico Eagle has reviewed CIRNAC comments on 2AM-MEL1631 Culvert 6 & 21 design report and understands CIRNAC has no comments with respect to design criteria.

With regards to the culvert typical sections, Agnico Eagle would like to clarify that this sealed engineering drawing has not been changed since it was issued in 2017 and that any revisions made in the field will be reflected in the as-built.

With my best regards,





Sara



**Sara Savoie** | Compliance Counselor

[sara.savoie@agnicoeagle.com](mailto:sara.savoie@agnicoeagle.com) | Direct 819.759.3555 x4608143 |

Agnico Eagle Mines Limited - 11600, rue Louis-Bisson - Mirabel, Quebec, Canada J7N 1G9

[agnicoeagle.com](http://agnicoeagle.com)    

[Quoted text hidden]