

July 21, 2020

VACUERPOC Dacac Dacar

Serving the communities of

DPV 224P Arctic Bay

6 AJCOPJUAD Clyde River

45C2V2AD Grise Fiord

 Δ $^{\text{L}}$ Igloolik

 $\Delta^{\varsigma}b \Delta^{\varsigma}$ Igaluit

PLTDC Kimmirut

ρουυΔο Kinngait

<°056)56 Pangnirtung

LcUTCC-P Pond Inlet

SPPSPCS495P Qikiqtarjuaq

46C7V2049 Resolute Bay

50P2956 Sanikiluag

50-556 Sanirajak Assol Kubeisinova Christopher Murray

Technical Advisor **Environmental Regulatory and Compliance Manager**

Nunavut Water Board **Baffinland Iron Mines Corporation**

P.O. Box 119 2275 Upper Middle Road East, Suite 300

Gjoa Haven, NU Oakville, ON L6H 0C3 X0B 1.10

RE: QIA Updated Response to Baffinland's 200618 2AM-MRY1325 - Submission of **Construction Notification and IFC Submission - Mine Site Landfarm**

Dear parties,

The Qikiqtani Inuit Association (QIA) provides this updated response to the Nunavut Water Board's (NWB) and Baffinland Iron Mines Corporation (BIMC) regarding BIMC's response to comments on the Mine Site Landfarm Issued for Construction Drawings¹.

1. Contravention of IIBA Section 15.10.4

QIA has agreed to work with BIMC to develop a list of specific regulatory filings that are included in the intended scope of 15.10.4. If a future contravention occurs, QIA will identify the issue for relevant parties.

2. Security Estimate for the Mine Site Landfarm

QIA is satisfied with BIMC's response.

3. Determination of Cell Storage Capacity

QIA is satisfied with BIMC's response.

4. Geological and Hydrogeological Considerations

QIA requests that the Construction Summary Report include confirmations of the bedrock geology, surficial geology, permafrost conditions, and groundwater flow dynamics assessments detailed in the Knight Piésold report².

5. Analogous Lined Facilities

QIA requests that BIMC confirm what monitoring (e.g., groundwater) will be completed to confirm liner integrity. Furthermore, what action levels and thresholds would trigger additional mitigation should contaminants be identified. This may be included in the

¹ Baffinland (2020). [Letter] RE: Response to Comments on the Issued for Construction Drawings – Mine Site Landfarm. Mary River Project, Type 'A' Water Licence - 2AM-MRY1325 - Amendment No. 1. July 13, 2020.

² Knight Piésold (2020). Mary River Project – Mine Site Landfarm – Design Brief and IFC Drawings. June 16, 2020.

VScUZePOC Dacac Dodogl

Serving the communities of

 $\nabla_{P} V Q_{e} A_{P}$ Arctic Bay

6001C42069 Clyde River

45CJQP AD Grise Fiord

 Δ^{L} Igloolik

 $\Delta^{\varsigma}b \Delta^{\varsigma}$ Igaluit

brLbc Kimmirut

ParLAC Kinngait

<°056)56 Pangnirtung

LcUTCC-P Pond Inlet

SPPSPCS44SP Qikiqtarjuaq

4PC7VCD4P Resolute Bay

50P2956 Sanikiluag

50-556 Sanirajak construction summary report and could be added to the AEMP during the adaptive management ICA work.

6. Construction and Post-Construction Monitoring Refer to QIA-5.

7. Commercial Lease Operations Guide QIA is satisfied with BIMC's response.

Sincerely,

Chris Spencer

Manager, Regulatory Affairs