



NWB Tools

Robert Hunter &lt;robert.hunter@nwb-oen.ca&gt;

---

## 2AM-MRY1325 2022 Geotechnical Inspection Report No. 2

---

**Robert Hunter** <robert.hunter@nwb-oen.ca>

Mon, Nov 7, 2022 at 3:20 PM

To: Connor.Devereaux@baffinland.com, Sylvain.Proulx@baffinland.com

Bcc: Distro Mary River &lt;distro-2am-mry@nwb-oen.ca&gt;

Good afternoon,

The Nunavut Water Board acknowledges receipt November 4, 2022 of the 2022 Geotechnical Inspection Report No. 2, for Baffinland Iron Mines Corporation water licence No: 2AM-MRY1325, it can be found at the link below:

<ftp://ftp.nwb-oen.ca/registry/2%20MINING%20MILLING/2A/2AM%20-%20Mining/2AM-MRY1325%20BIMC/3%20TECH/9%20MONITORING%20%28I%29/I%2012>

The Nunavut Water board is aware that a number of web browsers are no longer supporting File Transfer Protocol (ftp). If you are having difficulty accessing our FTP site you may need to download an FTP application. We have been recommending the FileZilla Client below to access the files, which is a free and open source application. A link can be found below:

<https://filezilla-project.org/>

This submission is distributed for information only.

Regards,

Robert Hunter  
Licence Administrator