



Richard Dwyer <richard.dwyer@nwb-oen.ca>

*****Follow-up*** Reportable Spill at Whale Tail Mine - 2023-06-15_250L Hydraulic Oil**

'Samuel Tapp' via Licensing Department <licensing@nwb-oen.ca>

Wed, Jul 12, 2023 at 7:07 AM

Reply-To: Samuel Tapp <samuel.tapp@agnicoeagle.com>

To: "Arsenault,Robert (ECCC)" <Robert.Arsenault2@ec.gc.ca>, Rowan Woodall <rowan.woodall@agnicoeagle.com>, Meadowbank Reportable Spill <Meadowbank.reportable.spill@agnicoeagle.com>, Emily Koide <ekoide@nirb.ca>, "tarko@nirb.ca" <tarko@nirb.ca>, "Didham,Curtis (ECCC)" <Curtis.Didham@ec.gc.ca>, "Seeteenak,Shauna (ECCC)" <Shauna.Seeteenak@ec.gc.ca>, Jeff Hart <landsbaker@kivalliqinuit.ca>, "Amsel, Kyle" <Kyle.Amsel@rcaanc-cimac.gc.ca>, Spills Govern <spills@gov.nt.ca>, "Imanzo@kivalliqinuit.ca" <Imanzo@kivalliqinuit.ca>, "joseph.monteith@rcaanc-cimac.gc.ca" <joseph.monteith@rcaanc-cimac.gc.ca>

Hi Robert,

We appreciate you bringing this matter to our attention. I acknowledge that the error was made on my part, and AEM had no intention of reporting this incident under the Fisheries Act.

We sincerely apologize for any confusion caused.

Regards,



Samuel Tapp | Environment Coordinator

samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com

Sent from Amaruk

From: Arsenault,Robert (ECCC) <Robert.Arsenault2@ec.gc.ca>

Sent: Wednesday, July 12, 2023 7:27 AM

To: Samuel Tapp <samuel.tapp@agnicoeagle.com>; Rowan Woodall <rowan.woodall@agnicoeagle.com>; Meadowbank Reportable Spill <Meadowbank.reportable.spill@agnicoeagle.com>; Emily Koide <ekoide@nirb.ca>; tarko@nirb.ca; Didham,Curtis (ECCC) <Curtis.Didham@ec.gc.ca>; Seeteenak,Shauna (ECCC) <Shauna.Seeteenak@ec.gc.ca>; Jeff Hart <landsbaker@kivalliqinuit.ca>; Amsel, Kyle <Kyle.Amsel@rcaanc-cimac.gc.ca>; Spills Govern <spills@gov.nt.ca>; Imanzo@kivalliqinuit.ca; joseph.monteith@rcaanc-cimac.gc.ca

Subject: [EXTERNAL] Re: ***Follow-up*** Reportable Spill at Whale Tail Mine - 2023-06-15_250L Hydraulic Oil

CAUTION: EXTERNAL

Hi Samuel,

I see that your email states that the incident was being reported under the Fisheries Act in addition to the requirements of the conditions of the Nunavut Water Board Licence.

Was it AEM's intention to report this under the Fisheries Act?

Thank you,

Rob Arsenault

Enforcement Officer | Agent d'application de la loi

Environment and Climate Change Canada | Environnement et Changement Climatique Canada

Enforcement Branch | Direction générale de l'application de la loi

Ontario Region | Région de l'Ontario

Government of Canada | Gouvernement du Canada

Canada Centre for Inland Waters | Centre canadien des eaux intérieures

Wastewater Technology Centre | Centre de technologie des eaux usées

867 Lakeshore Rd.

Burlington, Ontario, L7S 1A1

Office | Bureau: 289-313-6701; Mobile | Mobile: 867-222-1433

E-Mail | Courriel: robert.arsenault2@ec.gc.ca

Website | Site Web www.ec.gc.ca

From: Samuel Tapp <samuel.tapp@agnicoeagle.com>

Sent: July 11, 2023 3:48 PM

To: Rowan Woodall <rowan.woodall@agnicoeagle.com>; Meadowbank Reportable Spill <Meadowbank.reportable.spill@agnicoeagle.com>; Emily Koide <ekoide@nirb.ca>; tarko@nirb.ca <tarko@nirb.ca>; Didham, Curtis (ECCC) <Curtis.Didham@ec.gc.ca>; Arsenault, Robert (ECCC) <Robert.Arsenault2@ec.gc.ca>; Seeteenak, Shauna (ECCC) <Shauna.Seeteenak@ec.gc.ca>; Jeff Hart <landsbaker@kivalliqinuit.ca>; Amsel, Kyle <Kyle.Amsel@rcaanc-cirnac.gc.ca>; Spills Govern <spills@gov.nt.ca>; Imanzo@kivalliqinuit.ca <Imanzo@kivalliqinuit.ca>; joseph.monteith@rcaanc-cirnac.gc.ca <joseph.monteith@rcaanc-cirnac.gc.ca>

Subject: ***Follow-up*** Reportable Spill at Whale Tail Mine - 2023-06-15_250L Hydraulic Oil

Good afternoon,

Please find attached information as a follow up to a spill report, number 2023-257, submitted June 16, 2023, by Agnico Eagle Meadowbank Complex.

This detailed report is submitted to the inspectors in compliance with the conditions required by Nunavut Water Board License 2AM-WTP1830, Part H, item 8 (c), and Subsection 38(7) of the Fisheries Act.

If you require further information or have questions, please do not hesitate to contact the undersigned.

Regards,



Samuel Tapp | Environment Coordinator

samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     

Sent from Amaruk

From: Rowan Woodall <rowan.woodall@agnicoeagle.com>

Sent: Friday, June 16, 2023 1:32 PM

To: Meadowbank Reportable Spill <Meadowbank.reportable.spill@agnicoeagle.com>; Emily Koide <ekoide@nirb.ca>; tarko@nirb.ca; Didham, Curtis (ECCC) <Curtis.Didham@ec.gc.ca>; Arsenault, Robert (ECCC) <Robert.Arsenault2@ec.gc.ca>; shauna.seeteenak@ec.gc.ca; Jeff Hart <landsbaker@kivalliqinuit.ca>; Amsel, Kyle <Kyle.Amsel@rcaanc-cirnac.gc.ca>; Spills Govern <spills@gov.nt.ca>; Imanzo@kivalliqinuit.ca; joseph.monteith@rcaanc-cirnac.gc.ca

Subject: Reportable Spill at Whale Tail Mine - 2023-06-15_250L Hydraulic Oil

Good day,

Attached is a spill report depicting an event, Hydraulic Oil spill, which took place on June 15, 2023 at Agnico Eagle Mines Ltd., Whale Tail Mine.

This report is being reported as required by the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, item 8 (b) pursuant to subsection 12(3) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

This report is also being reported as required by the Government of Nunavut's, Environmental Protection Act paragraph 5.1(a).

A follow up report will be submitted following the completion of the corrective actions as required by Nunavut Water Board License 2AM-WTP1830, Part H, item 8 (c).

If you require further information or have questions, please do not hesitate to contact the undersigned.

Regards,



Rowan Woodall | Environmental Coordinator

rowan.woodall@agnicoeagle.com | Direct 819.759.3555 | 4606744

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C

0A0

agnicoeagle.com     