



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
Fax: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᓂᓕᓂᓪ
NUNAVUT IMALIRIYIN KATIMAYINGI
NUNAVUT WATER BOARD
OFFICE DES EAUX DU NUNAVUT

File No: 2BB-BOS0712/TR/A1

March 4, 2008

By email

Mr. John Wakeford
Vice President Exploration
Hope Bay Mining Ltd.
300-889 Harbourside Drive
North Vancouver, BC V7P 3S1
Email: jwakeford@miramarmining.com

Subject: INAC Inspection August 2007 and MHBL Response to Inspection

Dear Mr. Wakeford:

The Nunavut Water Board ("NWB") acknowledges receipt of an Inspection Report from INAC dated November 11, 2007, as well as a response from Miramar Hope Bay Ltd, dated December 20, 2007. These submissions have been placed on the NWB public registry and are available from the NWB ftp site at the following link: <http://nunavutwaterboard.org/ftp/>
Please refer to the folder entitled 2BB – Bulk Sampling / 2BB-BOS/Technical Review.

This report is forwarded to the distribution list for information only. Anyone wishing to provide comments can do so by return mail to the Manager of Licensing at the address indicated below.

Please forward all comments to licensing@nunavutwaterboard.org

Sincerely,

Original signed by:

Phyllis Beaulieu
Manager of Licensing

Cc: Kitikmeot Distribution List