



Ministère de l'Environnement

is on site. GPS or UTM coordinates should also be included in the site map to show the location of the camp with respect to other communities.

- 3) The proponent should provide quantities of all fuels and chemicals that were brought on site, in addition to any fuels left on site.
- 4) Comaplex Minerals should provide contact names, numbers, and addresses of the owner and site supervisor. The names and numbers of outside help and clean up specialists could also be included into the plan in the event of a large spill.
- 5) All drill holes, sumps, and disturbed areas should be capped, covered, and re-contoured to allow for natural re-vegetation.
- 6) The proponent must check for soil contamination due to fuel and chemical spills. All contaminated soils must be treated and disposed off properly, either on site or at a registered facility.
- 7) Samples and pictures should be taken before and after the abandonment and reclamation of the project area.

We thank the NWB for giving us the opportunity to review the spill contingency and abandonment and restoration plans for Comaplex Minerals Corporation. Please contact me if you have any further questions or comments.

Sincerely,

Original signed by

Ian Rumbolt
Coordinator, Environmental Assessment
Department of Environment
C/O Environmental Protection
Government of Nunavut
Box 1000, Stn. 1360
Iqaluit, NU, X0A 0H0
Phone: (867) 975-5924
Fax: (867) 975-5981
Email: irumbolt@gov.nu.ca