


Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-001
UTM 14Z 519506E 6940025N
April 24 2010 to 26 April 2010



10-LC-004 + 10-LC-005
UTM 14Z 519256E 6940022N
10-LC-004: May 1 2010 to May 4 2010
10-LC-005: May 5 2010 to May 7 2010



10-LC-002 + 10-LC-003
UTM 14Z 519285E 6940086N
10-LC-002: April 27 2010 to April 29 2010
10-LC-003: April 29 2010 to May 1 2010




10-LC-006 + 10-LC-007
UTM 14Z 519231E 6940031N
10-LC-006: May 8 2010 to May 10 2010
10-LC-007: May 10 2010 to May 12 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-008 + 10-LC-009
UTM 14Z 519173E 6940024N
10-LC-008: May 13 2010 to May 15 2010
10-LC-009: May 15 2010 to May 17 2010



10-LC-013 + 10-LC-014
UTM 14Z 517889E 6940582N
10-LC-013: May 24 2010 to May 26 2010
10-LC-014: June 22 2010 to June 24 2010



10-LC-010 + 10-LC-011 + 10-LC-012
UTM 14Z 518489E 6940333N
10-LC-010: May 18 2010 to May 20 2010
10-LC-011: May 20 2010 to May 21 2010
10-LC-012: May 22 2010 to May 23 2010



10-LC-015 + 10-LC-016
UTM 14Z 519109E 6940123N
10-LC-015: June 25 2010 to June 26 2010
10-LC-016: June 27 2010 to June 29 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos




10-LC-017 + 10-LC-018 + 10-LC-019
UTM 14Z 518625^E 6940384N
10-LC-017: June 29 2010 to July 2 2010
10-LC-018: July 2 2010 to July 4 2010
10-LC-019: July 4 2010 to July 5 2010



10-LC-023 + 10-LC-024 + 10-LC-025
UTM 14Z 518623E 6940266N
10-LC-023: July 11 2010 to July 12 2010
10-LC-024: July 12 2010 to July 14 2010
10-LC-025: July 15 2010 to July 17 2010



10-LC-020 + 10-LC-021 + 10-LC-022
UTM 14Z 518816E 6940205N
10-LC-020: July 5 2010 to July 6 2010
10-LC-021: July 7 2010 to July 8 2010
10-LC-022: July 8 2010 to July 10 2010



10-LC-026 + 10-LC-027 + 10-LC-028 + 10-LC-029
UTM 14Z 51846 6940397
10-LC-026: July 18 2010 to July 18 2010
10-LC-027: July 18 2010 to July 19 2010
10-LC-028: July 19 2010 to July 20 2010
10-LC-029: July 20 2010 to July 22 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-030 + 10-LC-031 + 10-LC-032 + 10-LC-033

UTM 14Z 519072 6940160

10-LC-030: July 22 2010 to July 24 2010

10-LC-031: July 24 2010 to July 26 2010

10-LC-032: July 26 2010 to July 27 2010

10-LC-033: July 27 2010 to July 30 2010



10-LC-037 + 10-LC-038 + 10-LC-039

UTM 14Z 519214 6940109

10-LC-037: August 7 2010 to August 8 2010

10-LC-038: August 9 2010 to August 10 2010

10-LC-039: August 10 2010 to August 13 2010



10-LC-034 + 10-LC-035 + 10-LC-036

UTM 14Z 519160 6940111

10-LC-034: July 30 2010 to August 1 2010

10-LC-035: August 1 2010 to August 3 2010

10-LC-036: August 3 2010 to August 7 2010



10-LC-040

UTM 14Z 519064 6940028

August 16 2010 to August 19 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-041 + 10-LC-042 + 10-LC-043 + 10-LC-044
UTM 14Z 519031 6940189

10-LC-041: August 20 2010 to August 21 2010

10-LC-042: August 21 2010 to August 22 2010

10-LC-043: August 22 2010 to August 23 2010

10-LC-044: August 23 2010 to August 24 2010



10-LC-048 + 10-LC-049

UTM 14Z 519523 6940057

10-LC-048: August 30 2010 to August 31 2010

10-LC-049: August 31 2010 to September 1 2010



10-LC-045 + 10-LC-046 + 10-LC-047

UTM 14Z 519375 6940097

10-LC-045: August 25 2010 to August 26 2010

10-LC-046: August 26 2010 to August 27 2010

10-LC-047: August 28 2010 to August 29 2010



10-LC-050 + 10-LC-051

10-LC-050: July 30 2010 to August 1 2010

10-LC-051: August 1 2010 to August 2 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-052 + 10-LC-053
10-LC-052: August 3 2010 to August 4 2010
10-LC-053: August 4 2010 to August 6 2010



10-LC-056 + 10-LC-057
UTM 14Z 518894 6940137
10-LC-056: August 8 2010 to August 10 2010
10-LC-057: August 10 2010 to August 13 2010



10-LC-054 + 10-LC-055
UTM 14Z 518945 6940241
10-LC-054: August 6 2010 to August 7 2010
10-LC-055: August 7 2010 to August 8 2010



10-LC-058
UTM 14Z 518879 6940222
August 13 2010 to August 16 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-059 + 10-LC-060 + 10-LC-061

UTM 14Z 518762 6940207

10-LC-059: August 16 2010 to August 20 2010

10-LC-060: August 20 2010 to August 22 2010

10-LC-061: August 22 2010 to August 25 2010



10-LC-065 + 10-LC-066 + 10-LC-067

UTM 14Z 518710 6940330

10-LC-065: August 29 2010 to August 30 2010

10-LC-066: August 30 2010 to September 1 2010

10-LC-067: September 1 2010 to September 2 2010



10-LC-062 + 10-LC-063 + 10-LC-064

UTM 14Z 518676 6940374

10-LC-062: August 26 2010 to August 27 2010

10-LC-063: August 27 2010 to August 28 2010

10-LC-064: August 28 2010 to August 29 2010



10-LC-068 + 10-LC-069

UTM 14Z 518580 6940291

10-LC-068: September 3 2010 to September 5 2010

10-LC-069: September 5 2010 to September 8 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos

10-LC-080: September 30 2010 to October 3 2010



10-LC-070 + 10-LC-071 + 10-LC-072 + 10-LC-073

UTM 518423 6940425

10-LC-070: September 8 2010 to September 9 2010

10-LC-071: September 9 2010 to September 10 2010

10-LC-072: September 11 2010 to September 13 2010

10-LC-073: September 14 2010 to September 16 2010

10-LC-081 + 10-LC-082

UTM 14Z 519600 6939989

10-LC-081: September 2 2010 to September 3 2010

10-LC-082: September 3 2010 to September 4 2010



10-LC-074 + 10-LC-075 + 10-LC-076

UTM 14Z 518536 6940428

10-LC-074: September 17 2010 to September 18 2010

10-LC-075: September 18 2010 to September 19 2010

10-LC-076: September 19 2010 to September 19 2010

10-LC-083 + 10-LC-084

UTM 14Z 519641 6939952

10-LC-083: September 5 2010 to September 6 2010

10-LC-084: September 6 2010 to September 7 2010

10-LC-077 + 10-LC-078 + 10-LC-079 + 10-LC-080

UTM 14Z 518513 6940268

10-LC-077: September 20 2010 to September 23 2010

10-LC-078: September 23 2010 to September 25 2010

10-LC-079: September 25 2010 to September 29 2010

10-LC-085 + 10-LC-086

UTM 14Z 519666 69399888

10-LC-085: September 7 2010 to September 8 2010

10-LC-086: September 8 2010 to September 9 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-087 + 10-LC-088 + 10-LC-089

UTM 14Z 519549 6939995

10-LC-087: September 10 2010 to September 11 2010

10-LC-088: September 11 2010 to September 12 2010

10-LC-089: September 12 2010 to September 14 2010



10-LC-096 + 10-LC-097 + 10-LC-098

UTM 14Z 519250 6939954

10-LC-096: September 25 2010 to September 27 2010

10-LC-097: September 27 2010, Lost September 28 2010

10-LC-098: September 29 2010 to October 2 2010



10-LC-090 + 10-LC-091

UTM 14Z 519473 940069

10-LC-090: September 14 2010 to September 15 2010

10-LC-091: September 15 2010 to September 16 2010



10-LC-099 + 10-LC-100

UTM 14Z 519469 6939948

10-LC-099: October 3 2010 to October 4 2010

10-LC-100: October 5 2010 to October 7 2010

10-LC-092 + 10-LC-093 + 10-LC-094 + 10-LC-095

UTM 14Z 519395 6940024

10-LC-092: September 17 2010 to September 19 2010

10-LC-093: September 19 2010 to September 20 2010

10-LC-094: September 21 2010, Lost September 22 2010

10-LC-095: September 22 2010 to September 25 2010

Lac Cinquante 2010 Drill Sites After Drilling Photos



10-LC-101 + 10-LC-102
UTM 14Z 519551 6939887
10-LC-101: October 8 2010 to October 10 2010
10-LC-102: October 10 2010 to October 12 2010



10-LC-112
UTM 14Z 518958 6940154
October 9 2010 to October 12 2010

10-NE-001
UTM 14Z 516599 6940564
October 13 2010 to October 15 2010



10-LC-110 + 10-LC-111
UTM 14Z 518420 6940306
10-LC-110: October 4 2010 to October 6 2010
10-LC-111: October 6 2010 to October 9 2010



10-L52-001
UTM 14Z 520670 6940105
October 13 2010 to October 16 2010