27 March 2007

**SENT VIA E-MAIL** 

licensing@nunavutwaterboard.org

Phyllis Beaulieu Manager of Licensing Nunavut Water Board P.O. Box 119 Gjoa Haven, NU X0B 1J0

Dear Ms. Beaulieu:

## RE: NWB WATER LICENCE NWB2BE-ANI0608 - ANIALIK PROPERTY, NU

Enclosed is the Annual Report for water licence NWB2BE-ANI0608 for the year 2007.

Please note the 2007 Annual Report was completed by North Arrow Minerals Inc. rather than by Strongbow Exploration Inc. In 2007 a Memorandum of Understanding was completed between North Arrow and Strongbow whereby North Arrow would be taking over as operator on Strongbow's Nunavut properties. A renewal application and assignment documents are being prepared and will be forwarded to your attention shortly.

Should you have any questions please contact me at (867) 873-8483 or via e-mail at <a href="mailto:gord@northarrowminerals.com">gord@northarrowminerals.com</a>.

Sincerely,

**NORTH ARROW MINERALS INC.** 

Horse Clarke

Gordon Clarke
President and CEO

NWB Annual	Report	Year being reported: 2007 ▼		
License No:	2BE-ANI0608	Issued Date:   May 31, 2006		
	Project Name:	Anialik		
	Licensee: Strong	gbow Exploration Inc.		
	Mailing Address:	Strongbow Exploration Inc. 800-625 Howe Street Vancouver, BC V6C 2T6		
		filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable):		
	North Arrow Minera	als Inc. (Strongbow and North Arrow signed Memorandum of 007; Licence to be assigned to N.Arrow)		
General Bacl	kground Information	n on the Project (*optional):		
	No work was conducted season.	cted under the authority of this license during the 2007 exploration		
with	Select ▼	Select		
A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.				
	Water Source(s): Water Quantity:	N/A  25 cu.m/day (including drilling)  N/A  25 cu.m/day (Quantity Allowable Domestic (cu.m)  Actual Quantity Used Domestic (cu.m)  Quantity Allowable Drilling (cu.m)  (including domestic use)  N/A  Total Quantity Used Drilling (cu.m)		
	Waste Management Solid Waste Dis Sewage Drill Waste Greywater Hazardous Other: Additional Details: N/A			

A 11 /	
A list o	f unauthorized discharges and a summary of follow-up actions taken.  Spill No.:  N/A  (as reported to the Spill Hot-line)
	Date of Spill: N/A
	Date of Notification to an Inspector: N/A
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
	As no work was conducted under the authority of this license during 2007 there were no occurences of unauthorized discharges.
	The occurences of unauthorized discharges.
Revision	ons to the Spill Contingency Plan  SCP submitted and approved - no revision required or proposed  T
	SCP submitted and approved - no revision required or proposed
	Additional Details:
	No revisions were made to the Spill Contingency Plan during 2007
Revision	ons to the Abandonment and Restoration Plan
	AR plan submitted and approved - no revision required or proposed
	Additional Details:
	No revisions were made to the Abandonment and Restoration Plan during 2007.
Progre	ssive Reclamation Work Undertaken
	Additional Details (i.e., work completed and future works proposed)
	N/A
Results	s of the Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each
	location where sources of water are utilized;
	Not Applicable (N/A)      ▼
	Additional Details:
	N/A
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each
	location where wastes associated with the licence are deposited;
	Not Applicable (N/A)   ▼
	Additional Details:
	N/A

	Results of any additional sampling and/or analysis that was requested by an Inspector
	No additional sampling requested by an Inspector or the Board
	Additional Details: (date of request, analysis of results, data attached, etc)
	N/A
Any other de	etails on water use or waste disposal requested by the Board by November 1 of the year ed.
	No additional sampling requested by an Inspector or the Board
	Additional Details: (Attached or provided below)
	N/A
Any respons	es or follow-up actions on inspection/compliance reports
	No inspection and/or compliance report issued by INAC   ▼
	Additional Details: (Dates of Report, Follow-up by the Licensee)
	No work was conducted under the authority of this license during the 2007 exploration season and therefore no inspection was conducted.
Any addition	al comments or information for the Board to consider
Date Submit Submitted/P Contact Info	repared by: Gordon Clarke, President, North Arrow Minerals Inc.