



NWB 2009 and 2010 Annual Reports  
License 2BE-BAF0611  
Issued July 10, 2006  
Licencee: Burnstone Ventures Inc.  
Suite 800  
1199 West Hastings St  
Vancouver BC

Report Filing by Apex Geoscience Ltd., Geological Consultants for Burnstone Ventures Inc.

		Latitude	Longitude
<b>Water Source</b>	Erichsen Lake	70° 56 2'.1"	80°10'49.7"
<b>Grey water and sewage</b>	Pingjuak Camp	70°56'4"	80°11'3"

	2009	2010
<b>Quantity Allowable domestic use</b>	2.5 m <sup>3</sup> /day	2.5 m <sup>3</sup> /day
<b>Actual Quantity domestic use</b>	0 m <sup>3</sup> /day	0.5m <sup>3</sup> /day
<b>Total domestic use</b>	0 m <sup>3</sup>	1.5 m <sup>3</sup>

#### **Additional Details:**

Water was pumped from Erichsen Lake into a holding tank in camp for daily use.  
There was no drilling in 2009 or 2010.

#### **Waste Management and Disposal**

Sewage and grey water sumps were monitored to ensure capacity was not exceeded.  
Combustible and non-combustible wastes were flown out.

#### **Water Use Inspection Report**

July 14, 2009 inspection report noted areas of non-compliance.  
Please see attached Compliance Status Report.  
Plans are in place for remediation in 2011.

#### **Plan Revisions**

A revised Spill Contingency and Abandonment and Restoration Plan were submitted to the NWB in July 2011 with a license renewal application.