

March 25, 2009

Nunavut Water Board  
P.O. Box 119  
Gjoa Haven, NU  
X0B 1J0  
Tel: (867) 360-6338  
Fax: (867) 360-6369

Email: [licensing@nunavutwaterboard.org](mailto:licensing@nunavutwaterboard.org)

**Re: NWB Licence No. 2BE-BOR0813**

---

To Whom It May Concern:

Please find attached a resubmittal of Indicator Minerals Inc.'s Abandonment and Restoration Plan and Spill Contingency Plan for its Borden Project, Baffin Island, NU, in accordance to your guidelines specified in NWB Licence No. 2BE-BOR0813, dated December 15, 2008 and received March 10, 2009.

As per the issued specifications, the Abandonment and Restoration Plan has been completely redone, and the Spill Contingency Plan has been changed as per the following:

Page 1, Section 1.0: amended introduction  
Page 1, Section 2.0, 2.1: list of camp facilities  
Pages 4 & 5, Section 3.1: location of size and capacity of fuel storage area(s)  
Pages 5 & 6, Section 5.1: identification of person in charge and 24-hour contact person  
Page 6, Section 5.3: addition of GN-D0E to chain of command list  
Page 11, Section 7.0: inclusion of spill equipment locations  
Appendix 3: figure of potential camp setup, including location of fuel storage location

In addition to the above, a new property location figure and a change to the original Appendix A: Non-Technical Summary is included, as land tenure and timing for the Borden project have changed since the original NWB Application was submitted. Please do not hesitate to call or email me if you have any additional questions or comments (email address: [andream@indicatorminerals.com](mailto:andream@indicatorminerals.com)).

Sincerely,  
**Indicator Minerals Inc.**

Andrea Maynes  
Project Geologist

Encs/Spill Contingency Plan, Abandonment and Restoration Plan, Property Figure, Addendum to Appendix A

275 - 1075 West Georgia Street  
Vancouver, BC V6E 3C9  
Canada

T. 604.331.4605  
F. 604.331.4654  
T.F. 1.877.331.4605  
[www.indicatorminerals.com](http://www.indicatorminerals.com)