

NWB Annual Report

Year being reported:

2021

License No: Issued Date:
Expiry Date:

Project Name:

Licensee:

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	<input type="text" value="Various"/>	
Water Quantity:	<input type="text" value="9125"/>	Quantity Allowable Domestic (cu.m) annual
	<input type="text" value="0"/>	Actual Quantity Used Domestic (cu.m)
	<input type="text" value="80665"/>	Quantity Allowable Drilling (cu.m) annual
	<input type="text" value="0"/>	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- Solid Waste Disposal
- Sewage
- Drill Waste
- Greywater
- Hazardous
- Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Four spills were recorded in 2021.

Two spills were unfiltered water release from fuel storage berms due to broken/plugged components. Released water had no odour, taste or visible sheen. Components were repaired and replaced.

One spill was the result from drips from a helicopter refuelling hose (100ml). The fourth spill was the result of a cracked plastic hydraulic oil pail. In these instances, the soil was collected in containers and stored for future disposal in 2022.

Spills are recorded as 2022001, 202200002, 20210505 and 2022003.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

No revisions.

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

No revisions

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Progressive reclamation is undertaken at the conclusion of each program. Work sites and camp facilities are clean, organized and well maintained. Additional maintenance will need to be conducted in 2022 as the camp will have been unoccupied for approximately three years.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below

Additional Details:

No water utilized in 2021 for domestic or drill purposes.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below

Additional Details:

Domestic waste generated in 2021 brought to Iqaluit for disposal. Quantity of absorbent pads and soil stored in large quonset for dispose in 2022.

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional sampling requested by an Inspector or the Board (See below)

Additional Details: (date of request, analysis of results, data attached, etc)

Plans had been to re-sample a 2017 spill site (#2017-320) however weather conditions on the scheduled sampling day prevented this from occurring. Previous sampling at the location from 2019 was within regulatory limits. This was to be a confirmation sample and will be taken in 2022.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

No additional sampling

Any responses or follow-up actions on inspection/compliance reports

Select

Additional Details: (Dates of Report, Follow-up by the Licensee)

No CIRNAC or ECC inspections in 2021

Any additional comments or information for the Board to consider

No water utilized in 2021. Payments for 2021 will be made by creditcard.

--

Date Submitted:
Submitted/Prepared by:
Contact Information:

February 7, 2022
David Willis
Tel: (604) 836-3284
Fax:
email: david.willis@debeersgroup.com