



NWB Tools

Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

Nunavut Water Licence 2BE-CYG0406 - Follow Up

1 message

Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>

Thu, May 15, 2014 at 9:21 AM

To: ebeukman@pendergroup.ca

Cc: Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

Hello Eugene,

To follow up on our conversation today, I would like to confirm that Pure Gold Minerals is now Burnstone Ventures Inc. If this is correct, would you please submit documentation of this to the Nunavut Water Board for their records. The outstanding licence 2BE-CYG0406 was issued in 2004 to Pure Gold Minerals Inc. and was never changed.

Attached you will find the 2012 Inspection Report that was issued, which noted wooden debris and old empty drums at a fuel cache location (coordinates are given in the report).

Please confirm receipt of this e-mail and report, and please notify me when Burnstone has made arrangements to complete the required work. Please note that while the licence is expired, Burnstone remains responsible for completing the site clean-up. This licence cannot be cancelled until such time as this work is completed.

If you have any questions, please don't hesitate to contact me.

Regards,

Eva Paul

Water Resources Officer | Agent des ressources hydriques

Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada

Nunavut Regional Office | Bureau régional du Nunavut

Building 918, PO Box 100 | Édifice 918, CP 100

Iqaluit, NU X0A 0H0

Phone | Tél. : [867-975-4548](tel:867-975-4548)

Cell | Mobile: [867-222-6490](tel:867-222-6490)

Fax | Téléc. : [867-979-6445](tel:867-979-6445)

Eva.Paul@aandc-aadnc.gc.ca



**IQALUIT-#559755-v1-IQALUIT-#559749-V1-2BE-
CYG0406_INSPECTION_FORM_JULY_15_2012_PDF.PDF**
688K