

---

**From:** "Michelle Johnson" <johnsonmi@inac.gc.ca>  
**To:** <rbecker@polarnet.ca>  
**Sent:** Monday, February 25, 2002 8:27 AM  
**Subject:** Re: NWB2GEO9702-Assignment  
Hi Rita,

I apologize for my oversight on the assignment comments. We have no concerns regarding the assignment of the licence; however, the fact that the security has not been paid is definitely an issue. When the licence is reassigned, we will require that the security (\$100,000.00 if that is still an acceptable value) is promptly received by our office.

Please let me know if you require anything further.

-Michelle

Michelle Johnson, M.Sc.  
Kitikmeot and Kivalliq Regional Coordinator  
Department of Indian Affairs and Northern Development  
P.O. Box 2200  
Iqaluit, NU X0A 0H0  
ph: 867-975-4548 fx: 867-975-4560

>>> "Rita Becker" <[rbecker@polarnet.ca](mailto:rbecker@polarnet.ca)> 02/18/02 03:56PM >>>

Hi Paul,

I know Michelle is out of town right now, but I just wanted to double check about the assignment for this licence to Kinross. We didn't receive any comments from DIAND but I did get a request from Michelle awhile back asking about the security for this. I checked our records and was able to determine that we hadn't received any security - or had no records of anything - from any of the previous companies. Michelle indicated that this was a problem, but I haven't heard anything back and the deadline for comments was Feb 8/02.

Please advise. Thanks.

Rita Becker  
Licensing Administrator  
Nunavut Water Board  
Phone: 867-360-6338  
Fax: 867-360-6369