

INUNGNUT TUHAQHITYUN IHUAQHIGIAGUTIKHAMUT TUKHIQTUGUN

Sabina Guulit Silverlu Kuapurisan

Malikhugu Ilangani 55(1) tapkunani Nunavut Imaliginiqmun tapkuatlu Nunavut Nunap Qangani Piyungnauhiligiyyit Apiqhuiyigalaat Piquyat (“Piquyat”), tuhaqhittiyut tapkuat Sabina Guulit Silverlu Kuapurisan tunihiyut tukhiqtugutimik ihuaqhigiagutikhamut imaqmun laisauyumun tapkununga Nunavut Imailgiyyit Katimayit (Imaligiyyit) atuqniqmun imaqmik uvaluniit iqaqniq iqakunik imaqmun tapkununga havaktauyunut:

Titiqat Nappa: 2BE-GOO1015
Havaanguyuq: Goose Tahiq Havakviani
Nayugta: Hanimun: 65°32’40”N; Tukimun: 106°25’35”W
Pityuta: Ilavaliqnii Immap atuqnia
Qanugittuunia: “B”

Kinaliqak Inuk piyumayut hatqiqhihinagialgit hivuani **Januari 7, 2011** talvunga:

Maaniyauyuq Laisaligiyyimun
Nunavut Imaligiyyit Katimayit
P.O. Box 119, Gjoa Haven, NU X0B 1J0
Hivayauta: (867)360-6338; Faxkut (867)360-6369;
Kagitauyakut: licensing@nunavutwaterboard.org

Ayikutainik tamainik tukhiktugutauyumun titikanik piyungnaqtun aktuqtauyut piqatauyut, akikangitumik, atuqlugit tapkuat qagitaumatigut ftp qagitauyaqaqviani tapkunani tugagutini:

<ftp://nunavutwaterboard.org/1%20PRUC/2%20MINING%20MILLING/2B/2BE%20-%20Exploration/2BEGOO1015%20Sabina/1%20APPLICATION/2010%20Amendment%20/>

John Laitin, Maniyauyuq
Hivayauta: (604) 998-4175, Faxkut: (604) 998-1051;
Qagitauyakut: jlaitin@sabinagoldsilver.com

Tunihingitpan kiutyutimik taphumunga Tuhaqhityutmun Tukhiqtugutimun qangiknihaqtitlugu tamna taihimayuq pivikhaq pityutauniaoq tammainianik tapkuat pilaqniinut utiqviuyukhat, malikhugit Ilangani 58 talvunga 61) tapkunani Piquyani.