



Indian and Northern
Affairs Canada

Affaires indiennes
et du Nord Canada

INDUSTRIAL WATER USE INSPECTION REPORT

DATE: July 21/05COMPANY REP.: TedLICENSEE: (NWT) NW62HX0305LICENCE #: Wulfsberg Resource

WATER SUPPLY

Source: High LakeQuantity Used: UnknownMeter Rdg.: N/AIndicate: **A - Acceptable****U - Unacceptable****N/A - Not Applicable**Intake Facilities A
Flow Meas. Device N/AStorage Structures A
Conveyance Lines ATreatment Systems N/A
Pumping Stations ARecycling A
Modifications N/A

Comments: Water samples were taken at the intake on High Lake. Water is filtered before use by camp. Ted has promised to monitor the # of tanks of water that is used by the camp until metering is in place.

WASTE DISPOSAL

Tailings: N/ATailings Pond ☒Natural Lake ☒Underground ☐

Sewage:

Sewage Treat. System ☐Tailings Pond ☐Natural Water Body ☐IntermittentContinuous Discharge ☐Inter. Dischg. ☐

Solid Waste:

Open Dump ☐Landfill ☐Burn & Bury ☐Underground ☐Indicate: Flown out/off site.
A - Acceptable**U - Unacceptable****N/A - Not Applicable**Discharge Quality N/A
Decant Structures A
Dyke Inspections N/AConveyance Lines A
Pond Treatment N/A
Runoff Diversion N/ADisch. Meas. Dev. N/A
Dams, Dykes N/A
Erosion N/AFreeboard N/A
Seepage N/A
Spills N/A

Effluent Discharge Rate: _____

Samples Collected: _____

Comments: Solid waste is baled into 45 gallon drums & transported off site. White fuel/oil is also stored in 45 gallon drums until it can be shipped off site. One drum is stored by the main generator shed until full.

GENERAL CONDITIONS

Indicate: **A - Acceptable****U - Unacceptable****N/A - Not Applicable**Ore & Waste Rock Stockpiles _____
Geotechnical Inspection _____
Restoration Activities _____
Mine Water Discharge _____Records & Reporting _____
Posting, Signage _____
New Construction _____
Chemical Storage _____Surv. Net. Prog. _____
Contingency Plan _____
Fuel Storage _____
Annual Report _____

Comments: Refuelling stations at the helipads need to have secondary containment for fuel spills. The lower helipad is very close to the water & any spills that occur would almost definitely enter High Lake. The small refuelling station for snowmachines/boats is also

Violations of Act or Licence: The main concerns are the proximity of helipad refuelling stations to the water any spills would result in contamination of High Lake. The camp is cluttered because it space issues but no spills are evident & waste is generally shipped out regularly.

General Comments: more secondary containment to prevent spills. Grey water goes through two settling tanks before it is discharged over the top of the hill. Sewage waste is incinerated and all other hazardous waste is shipped off site. Spill pans have been installed at all accommodations tents and this is an improvement over last year.

Page 2 attached ☐ Yes ☐ No

Camp Manager
Licensee Representative's Title

SCOTT STEWART
Inspector's Name

[Signature]
Licensee Representative's Signature

[Signature]
Inspector's Signature