

MAY-23-2000 11:38

SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line

Phone/Dial (403) 920-8130

Fax/Telex (403) 873-8824

Northwest Territories

Spill Report

A Report date and time May 2000 10:00		B Date and time of spill (if known) May 4/00?		C ☒ Original report ☐ Update no. _____		Spill number 00-109	
D Location and map coordinates (if known) and direction (if moving) Hope Bay Joint Venture Boston Camp							
E Party responsible for spill Fred H Ross Ass.				PC LA OM TD SD		NUNAVUT WATER BOARD MAY 23 2000 PUBLIC REGISTRY	
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) Diesel fuel Max 5 gal							
G Cause of spill Leak in fuel tank of Bull Dozer							
H Is spill terminated? ☒ yes ☐ no		I If spill is continuing, give estimated rate No		J Is further spillage possible? ☒ yes ☐ no		K Extent of contaminated area (in square metres if possible) 2 meters X 2 meters	
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) Frozen ground				M Containment (natural depression, dykes, etc.) Frozen ground			
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials Surface fuel soaked up with newsprint. Will scope up frozen gravel pad where spill happened.							
O Do you require assistance? ☒ no ☐ yes, describe: _____				P Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife None			
Q Comments and/or recommendations Spill on Camp pad. Not on tundra or lake. Fuel tank on Bull Dozer was over filled. Warm weather made fuel expand. Fuel leaked from vent in fuel tank. We have moved the Dozer so to change the angle. Will pump out fuel from fuel tank. Fred H Ross person will be on site May 10 to inspect Dozer. Spill on South side of Crusher building						FOR SPILL LINE USE ONLY Lead Agency Spill significance Lead Agency contact and time Is this file now closed? ☐ yes ☐ no	
Reported by Ken Brophy		Position, Employer, Location Camp Manager / HBIU Boston Camp		Telephone 609 516-0254			
Reported to P.O. Box 1000		Position, Employer, Location P.O. Box 1000		Telephone P.O. Box			

MAY-23-2000 11:39

Northwest
Territories

Other Materials

A Report date and time May 15/2000		B Date and time of spill (if known) May 14/2000 15:50 hr		C ☒ Original report ☐ Update no. _____		Spill number 00-118	
D Location and map coordinates (if known) and direction (if moving) Incinerator area, HBSU Boston Camp				INTERNAL LA CM TA BS ED CEO BRD		MAY 23 2000 PUBLIC REGISTRY	
E Party responsible for spill Hope Bay Joint Venture				F Product(s) spilled and estimated quantity (provide metric volumes/weights if possible) Diesel Fuel			
G Cause of spill New employee put fuel inside incinerator chamber				H Is spill terminated? ☒ yes/ ☐ no			
I If spill is continuing, give estimated rate 1/2 barrel per hour				J Is further spillage possible? ☐ yes/ ☒ no			
K Extent of contaminated area (in square metres if possible) 4 meters X 4m				L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) Spill on frozen pad			
M Containment (natural depression, dykes, etc.) Crush rock pad				N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials Scooped-up surface fuel with cup & bucket. Soaked-up remaining fuel with Enviro-mat. Shoveled contaminated pad into 45 gal drums			
O Do you require assistance? ☒ no/ ☐ yes, describe: _____				P Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife None			
Q Comments and/or recommendations Spill was a result of miscommunication between Supervisor & employee. More extensive training will be provided in the future to prevent other incidents.						FOR SPILL LINE USE ONLY Lead Agency Spill significance Lead Agency contact and time Is this file now closed? ☐ yes/ ☐ no	
Reported by Ken Boppy		Position, Employer, Location Camp Manager, HBSU Boston		Telephone 604 2516-0254		Reported to _____	
Position, Employer, Location _____		Telephone _____		Reported to _____		Position, Employer, Location _____	

