



HOPE BAY JOINT VENTURE

Miramar Hope Bay Ltd. – Hope Bay Gold Corporation Inc.

311 West First Street, North Vancouver, B.C. V7M 1B5

Phone 604-985-2572 Fax 604-980-0731

VIA FACSIMILE (867)360-6369

October 2, 2000

Mr. Philippe di Pizzo
Executive Director
Nunavut Water Board
P.O. Box 119
Gjoa Haven, NU, X0E 1J0

Dear Mr. di Pizzo,

Re: Water Quality Report for Water Permit: NWB2HOP0002

This letter serves to report the results of open water samples collected pursuant to Part E, section 7 of the above noted water permit issued March 10, 2000 and amended August 22, 2000. The permit stipulates that once a month during the open water season, samples must be collected where grey water may potentially enter Windy Lake. The following table summarizes the results of the two samples collected from the shoreline water of Windy Lake.

Parameters	Windy Lake N. Down-slope from the latrines	Windy Lake S. Down-slope from greywater discharge and fuel cache
Sample Date	Aug. 30, 2000	Aug. 30, 2000
Physical Tests		
pH	7.8	7.8
Total Suspended Solids (mg/l)	<5	<5
Bacteriological Tests		
Coliform – Fecal (mpn/100ml)	2	0
Extractables		
Oil and Grease (mg/l)	5	<5
Organic Parameters		
BOD-5 (mg/l)	<5	<5

If you have any questions regarding this submission, please do not hesitate to contact the undersigned at hugh_r_wilson@hotmail.com or hwilson@miramarmining.com.

Sincerely,
Hope Bay Joint Venture

Hugh R. Wilson,
Manager, Environmental Affairs

