

MIRAMAR HOPE BAY LTD.

311 West First Street, North Vancouver, B.C. V7M 1B5 Canada Phone 604-985-2572 Fax 604-980-0731

ORIGINAL VIA E-MAIL

28 August 2002

Mr. Philippe di Pizzo Executive Director Nunavut Water Board, P.O. Box 119 Gjoa Haven, NU, X0E 1J0





Dear Mr. di Pizzo,

Re: July 2002 Monthly Report for Water License: NWB2HOP0207

Activities at the Windy Lake camp during the month of July focused on advanced exploration activities in the Doris Lake, Patch Lake and other target areas. The camp was operational from July 18-31 and the camp population during the report period was approximately 75 persons. Water sampling requirements were from the RBC discharge and in Windy Lake where this discharge potentially enters the lake.

Table 1 provides information for the RBC Sewage Discharge Point and Table 2 provides data on the "Windy Lake – Down-slope from RBC Sewage Discharge".

Rotating Biological Contactor (RBC) Sewage Discharge Point				
July 24				
Not done				
420				
3500000				
	July 24 Not done 420	July 24 Not done 420		

Extractables		
Oil and Grease (mg/l)	38.6	
Organic Parameters		
BOD-5 (mg/l)	201	

Table 2	WINDY LAKE -DOWNSLOPE FROM RBC-SEWAGE DISCHARGE				
Parameters					_
Sample Date	July 24				
Physical Tests					1
pH	7.83				
Total Suspended Solids (mg/l)	<3				
Bacteriological Tests					1
Coliform Bacteria – Fecal (Cfu/100ml)	Not done				
Extractables					*****
Oil and Grease (mg/l)	<.2				
Organic Parameters					-
BOD-5 (mg/l)	Not done				

There were no reportable spills for the report period.

With the above in mind, this letter is seen to meet full compliance with the above noted water license.

If you have any questions, please do not hesitate to contact the undersigned on the above numbers or 1-780-975-2550 or on e-mail at https://numbers.com.numbers.com. terrbear@powersurfr.com or hwilson@miramarmining.com.

Sincerely,

Hope Bay Joint Venture

Original signed by "H.R. Wilson"

Hugh R. Wilson,

Manager, Environmental Affairs