



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR February 20 2008		REPORT TIME 11:43 am		<input type="checkbox"/> ORIGINAL SPILL REPORT, OR <input checked="" type="checkbox"/> UPDATE # 1 TO THE ORIGINAL SPILL REPORT		REPORT NUMBER 08 - 061	
B	OCCURRENCE DATE: MONTH - DAY - YEAR February 19 2008		OCCURRENCE TIME 1100 pm					
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KTL303C056			WATER LICENCE NUMBER (IF APPLICABLE) NWB 2BE-HOP0712				
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Windy Lake Camp				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES MINUTES SECONDS			LONGITUDE DEGREES MINUTES SECONDS				
F	RESPONSIBLE PARTY OR VESSEL NAME Hope Bay Mining Limited		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION 300-889 Habourside Drive, North Vancouver, BC V7P 3S1					
G	ANY CONTRACTOR INVOLVED NA		CONTRACTOR ADDRESS OR OFFICE LOCATION NA					
H	PRODUCT SPILLED Treated RBC Effluent		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <0.5 cubic meters			U.N. NUMBER		
H	SECOND PRODUCT SPILLED (IF APPLICABLE) NA		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES NA			U.N. NUMBER		
I	SPILL SOURCE RBC Lift Station (HOP-2)		SPILL CAUSE Burnt out Lift sump pump			AREA OF CONTAMINATION IN SQUARE METRES 90 square meters		
J	FACTORS AFFECTING SPILL OR RECOVERY Frozen treated effluent		DESCRIBE ANY ASSISTANCE REQUIRED Managed in house			HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT No significant hazard		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The attached electronic report (Windy Camp Lift Station_Spill #08-061 Feb1908) provides details of HBML actions taken to date and provides information on the next stage of work currently in the planning phase.							
L	REPORTED TO SPILL LINE BY Matt Kawei	POSITION Snr Env Coordinator	EMPLOYER Hope Bay Mining LT	LOCATION CALLING FROM Windy Lake	TELEPHONE 604-759-2324			
M	ANY ALTERNATE CONTACT Mike Meyer	POSITION Director, ESR	EMPLOYER Newmont Mining LT	ALTERNATE CONTACT LOCATION Denver, USA	ALTERNATE TELEPHONE 303-945-6937			
REPORT LINE USE ONLY								
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YFILLLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130			
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> IA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED			
AGENCY		CONTACT NAME		CONTACT TIME		REMARKS		
LEAD AGENCY								
FIRST SUPPORT AGENCY								
SECOND SUPPORT AGENCY								
THIRD SUPPORT AGENCY								