

P.O. Box 360 Kugluktuk, NU X0B 0E0 Telephone: (867) 982-3310 Fax: (867) 982-3311 www.kitia.ca

Kugluktuk

Bathurst Inlet Kingaok 50°°U>°

Bay Chimo Umingmaktok ⊳୮∿Lьఏˤь

Cambridge Bay Ikaluktutiak ムらしらつい

Gjoa Haven Okhoktok ▷⁵७८¹⁵७̀⊃⁵७

> Taloyoak Cン⁵くく⁵⁶

Kugaaruk dU5≺b March 29, 2011

Phyllis Beaulieu Manager of Licencing Nunavut Water Board Gjoa Haven, NU X0B 1J0

Re: 110223 2BE-HOP0712 I16 Final Closure Plan Windy Camp and Patch Lake Facility - Kitikmeot Region

Via Email: <u>licensing@nunavutwaterboard.org</u>

Dear Ms. Beaulieu

The Kitikmeot Inuit Association (KIA) has reviewed HBML's Final Closure Plan Windy Camp and Patch Lake Facility. The KIA has engaged BGC Engineering (BGC) to assist us with the technical review of this plan, and BGC has submitted a detailed report to us. The BGC report (attached to this submission) identifies several concerns with HBML's closure plan.

The concerns are highlighted in text boxes in Section 3 of the BGC report. KIA cannot properly assess and manage risk on Inuit Owned Lands without details and/or clarifications addressing the concerns identified by BGC.

The KIA would like to thank the NWB for the opportunity to comment on this file. Please contact us if you have any questions.

Sincerely,

Luigi Torretti Senior Environment Officer Kitikmeot Inuit Association

Dep't of Lands & Environment