

File: 2BE-HRP1924

June 1, 2020

Peter Kuhn

Blue Star Gold Corp. & Inukshuk Exploration Inc.

1125-595 Howe St.

Vancouver, BC V6C 2T5

Sharleen Hamm

102-17910 55 Ave

Surrey, BC

V3S 6C8

Email: <u>kigold2010@gmail.com</u> Email: <u>sharleen@sharleenhamm.com</u>

RE: Licence No: 2BE-HRP1924 Type "B"; Hood River Project, Inukshuk Exploration

Inc.; 2019 Annual Report Review

Dear Peter Kuhn and Sharleen Hamm:

The Nunavut Water Board (NWB or Board) has completed the technical review of the 2019 Annual Report (Report) for Type "B" Water Licence 2BE-HRP1924 (Licence). The Report was received on May 7, 2020 from Inukshuk Exploration Inc. (Inukshuk Exploration or Licensee) and submitted as a requirement under Part B of the Licence.

Copies of all documents received during Report review can be accessed through the NWB's Public Registry and FTP site using the following link:

ftp://ftp.nwb-oen.ca/registry/2%20MINING%20MILLING/2B/2BE%20-%20Exploration/2BE-HRP1924%20Bluestar/3%20TECH/B%20GENERAL/2%20ANNUAL%20RPT/2019/

On May 22, 2020, the NWB distributed the Report to the Kitikmeot distribution list for information. No comments have been received to date. The Board has reviewed the Report and would like to note the following:

- a. The Licensee indicates that cuttings sumps were used; however, neither the location coordinates for these sumps nor the amount of Waste deposited in the sumps were included in the Report; and
- b. The Licensee did not conduct testing of the Effluent discharged at Monitoring Program Station HRP-1 as required under Part D, Item 12 of the Licence.

The Board requires that the Licensee eliminate the deficiencies noted above with the **2020 Annual Report**.

If you have any questions, please contact the undersigned at assol.kubeisinova@nwb-oen.ca or (867) 360 6338 (ext. 31).

Best regards,

Assol Kubeisinova Nunavut Water Board Technical Advisor

Cc: Distribution List – Kitikmeot