

Phyllis Beaulieu

From: Warbanski, Mark [Mark.Warbanski@areva.ca]
Sent: Tuesday, July 08, 2008 2:04 PM
To: craig.broome@ec.gc.ca; licensing@nunavutwaterboard.org; NingeonganD@inac-ainc.gc.ca; KusugakP@inac-ainc.gc.ca
Subject: AREVA Resources - Kiggavik Project
Attachments: Andrew July 6, 2008 002.jpg; Andrew July 6, 2008 010.jpg; Andrew July 6, 2008 010.jpg; Andrew Lake July 7 2008 008.jpg; local_survey_area.pdf; Andrew Locations.jpg

Hello all,

Here are some photographs of the site of the Andrew Lake sediment spill. AREVA has stopped all drilling in this area due to the sediment spill. Water samples were taken and are being sent to an accredited laboratory for analysis. We are also ordering silt curtains and sediment barriers for all other drilling activities for the Kiggavik Project. I hope our response was adequate and our corrective measures were correct for accessing the situation. We are happy to receive any and all feedback from all of you regarding this incident (improvements, suggestions).

The spill occurred at Andrew Lake on the Sissons property lease. The UTM Coordinates of the drill hole is: 14W 553384 7134863

The Lat/Long Coordinates are: lat:
 64.33548545668884 long: -97.89526750147954

Mark Warbanski, B.Sc.
 Coordinator, Environmental Health and Safety
 AREVA Resources Canada Inc.
 PH: 306-343-4043
 Site PH: 306-683-9843
 FX: 306-343-4044
mark.warbanski@areva.ca
 AREVA Group



Before printing this e-mail think if it is necessary

The information contained in this E-mail and any accompanying documents may contain information that is confidential or otherwise protected from disclosure. If you are not the intended recipient, please immediately alert the sender by reply e-mail and then delete this message, including any attachments. Any dissemination, distribution or other use of the contents of this message by anyone other than the intended recipient is strictly prohibited. For further information about AREVA please see our website at <http://www.arevaresources.ca>