

INUNGNIK TUHAQTITTITYUT LAISITAFFAAGUMAYUNIT
Coronation Minerals-kut

Malighugu Nakataq 55(1) Nunavut Imaqtigut Nunavut Nunap Qannganiitunut Piyunnautit Maligaat, Coronation Minerals-kut tunihiut tukhiunmingnik nutaangurumaplugu imaqtutikhamik laisitagumaplutik Nunavut Imalirinirmut Katimayinnut imaqtuqpagiamingni imakkurlutiglu umunga havariyauyumut:

Naunaitkuta #: **NWB2KUG0305**

Havaariyauyuq: Tahiryuami

Huqpaniinnia: Latitude: 67°15’-mit 67°45’-mut; Longitude: 115°45’

Huliut: Ukturlutik Ikuutagahuat

Qanurittuq: “B”

Ilauyumayut inuit ilauquyauyut nipliutikhaqarumik hivuagut **Aagasi 13, 2005** umunga:

Laisilirinirmut Atannguyaq

Nunavut Imaliriyiit

Titiqqilviat 119, Urhuqtuq, Nunavut X0B 1J0

Hivayautaa: (867) 360-6338; Kayumikturut: (867) 360-6369;

Qarittauyakkut: licensing@nwb.nunavut.ca

Atjinngit titiqqat tukhiutip piyaunginnagialgit aktumayauniaqtunit timinit, akiittumik, qarittauyakkut uvani <http://ftp.nunavut.ca> iluani “nwb” titigaqarvingmi “NWB2 EXPLORATION” iluliqpiangani “NWB2KUG” turaqtittivigiluguluunniit:

Rory Calhoun, Coronation Minerals-kuni

Hivayautaa: (416) 628-5936, Kayumikturut: (416) 628-5935

Qarittauyakkut: r_Calhoun@rogers.com

Kiunngitkuffi umunga Tuhaqtittiyunmut Tukhiunmut titigarvikhaq umiktinagu tammarniaqtuq ayunngityut himmauhiqtaunirmut, ataagut Nakatap 58-mit 61-mut Maligarmi.

