



ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᓂᓕᓂᓪ  
NUNAVUT WATER BOARD  
NUNAVUT IMALIRIYIN KATIMAYINGI  
OFFICE DES EAUX DU NUNAVUT

**File No.:** Licence No. 2BE-MLL1217/TR/B2

July 22, 2016

John Laitin, Manager of Technical Services  
Sabina Gold and Silver Corp.  
Suite 375, 555 Burrard Street  
Box 220  
Vancouver, BC V7X 1M7

E-mail: [jlaitin@sabinagoldsilver.com](mailto:jlaitin@sabinagoldsilver.com)

**Subject: Licence No. 2BE-MLL1217 – Submission of 2012, 2014, and 2015 Annual Reports by Sabina Gold and Silver Corp. for the Wishborne Malley Project**

---

Dear Mr. Laitin:

The Nunavut Water Board (NWB or Board) has completed its review of the 2012, 2014, and 2015 Annual Report (Reports) submitted by Sabina Gold and Silver Corp., in 2013, 2015, and 2016, respectively, to satisfy relevant requirement in the Licence issued to the Wishborne Malley Project, an exploration project located approximately 50 kilometres west of the Back River Project, in the Kitikmeot Region, Nunavut.

The review determined that the Reports are generally complete and consistent with the reporting requirements under Part B, Item 2, of Licence No. 2BE-MLL1217. The Board notes that while onsite activities occurred during the 2012 field season, no field activities were conducted during the 2014 and 2015 periods, as indicated in the respective Reports submitted by the Licensee.

Copies of the Reports, which was distributed publicly for information purposes shortly following receipt, can be accessed through the NWB's public registry and File Transfer Protocol (FTP) site using the following link:

[ftp://ftp.nwb-oen.ca/registry/2%20MINING%20MILLING/2B/2BE%20-%20Exploration/2BE-MLL1217%20Sabina/3%20TECH/1%20GENERAL%20\(B\)/2%20ANNUAL%20RPT/2015/160403%202BE-MLL1217%202015%20Annual%20Report%20Form-IAAE.pdf](ftp://ftp.nwb-oen.ca/registry/2%20MINING%20MILLING/2B/2BE%20-%20Exploration/2BE-MLL1217%20Sabina/3%20TECH/1%20GENERAL%20(B)/2%20ANNUAL%20RPT/2015/160403%202BE-MLL1217%202015%20Annual%20Report%20Form-IAAE.pdf)

Apart from the above, the Licensee is reminded that the Board has not been in receipt of the 2013 Annual Report. The Licensee is therefore advised to provide the Board with a copy of this report within thirty (30) days from the date of this correspondence.

If you have any questions related to the above, please contact the NWB's Licensing Department at (867) 360-6368 or by email to [licensing@nwb-oen.ca](mailto:licensing@nwb-oen.ca).

Regards,

(for) Sean Joseph  
Senior Technical Advisor

cc: Kitikmeot Distribution List