

## NWB Annual Report

Year being reported: 2011 ▼

License No: 2BE-NQN0914

Issued Date: June 18, 2009

Expiry Date: October 31, 2014

Project Name: Nanuq North

Licensee: Bluestone Resources Inc.

Mailing Address: Unit 1020 - 800 West Pender Street  
Vancouver, British Columbia  
V6C 2V6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Peregrine Diamonds Ltd., Joint venture partner and now project operator.

## General Background Information on the Project (\*optional):

One diamond drill hole was completed in July 2011.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s): Local Water Source - 2.7 km long lake

Water Quantity:	Quantity Allowable Domestic (cu.m)
	Actual Quantity Used Domestic (cu.m)
	Quantity Allowable Drilling (cu.m)
	Total Quantity Used Drilling (cu.m)

## Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☒ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

No camp has been established though one has been authorized.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills or unauthorized discharges in 2011

#### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

For 2011 there were no revisions to the existing spill plan as the Project and Project objectives have not changed.

#### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

For 2011 there were no revisions to the existing abandonment and restoration plan as the Project and Project Objectives have not changed

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

All drill materials and drill core removed from drill site.

#### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below ▼

Additional Details:

Drill Hole: NNQ-411:

Latitude (y) = 65 degrees 38 minutes 49.3379 seconds

Longitude (x) = -90 degrees 56 minutes 10.1656 seconds

Drilled July 27, 2011 to August 1, 2011

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below ▼

Additional Details:

A natural land depression was utilized to contain drill water with cuttings.

Latitude (y) = 65 degrees 38 minutes 49.452 seconds

Longitude (x) = -90 degrees 56 minutes 12.084 seconds

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Not Applicable

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Not Applicable

**Any responses or follow-up actions on inspection/compliance reports**

Select ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Not applicable

**Any additional comments or information for the Board to consider**

No additional Comments

**Date Submitted:**

July 26, 2012

**Submitted/Prepared by:**

David Willis

**Contact Information:**

Tel: (604) 408-8880

Fax: (604) 408-8881

email: [dave@pdiam.com](mailto:dave@pdiam.com)