

Follow-up: 2BE-NTI0507 Inspection of July 12, 2014

Cynthia Ene <cynthia.ene@nwb-oen.ca>

Thu, Sep 24, 2015 at 4:08 PM

To: mmacmorran@northarrowminerals.com

Cc: Licensing Department <licensing@nwb-oen.ca>, Karén Kharatyan <karen.kharatyan@nwb-oen.ca>

Good Afternoon Mike,

Per your email dated August 6th 2015, I followed up with Eva Paul, the Water Resources Officer with AANDC. Please find her response below.

As indicated, Strongbow does not have any obligation to do any further cleanup than what is identified in the inspection report. Perhaps, while on site conducting your final restoration of the flycamp, you can address what ever you can with respect to the drill collars, but you are clearly not obligated to do so per Ms. Paul's email.

Sincerely,



Cynthia Ene, MBA, P.Eng.- ٧٩٢٤ ٤٤٥٧

Technical Advisor- Conseillère Technique

ᐱᓗᑦᑐᕋᕈᕆᓂᓄᔪᓂᓄᔭ ᐃᑲᕐᑎ- Piliuaqnaqtuliginigmun Ikayuqti

NUNAVUT WATER BOARD - OFFICE DES EAUX DU NUNAVUT

ᓄᓇᓂᓪ ᐃᐱᓕᓂᓪ ᑲᑎᐱᓪᓴᓯ - NUNAVUT IMALIRIYIN KATIMAYINGI

www.nwb-oen.ca

P.O. Box 119

Gjoa Haven, NU, X0B 1J0

C.P. 119

Gjoa Haven (Nunavut), X0B 1J0

၂၂၆၁၁၁ ၁၁၁

▷(12) \mathbb{A}^1 , \mathbb{A}^2 X013 110

Titigacaqvia 119

Ughmugma, NU, X013 110

Tel / Téléphone / ལྷན་སྐྱོད་ / Hivayauta: (867) 360-6338 | Fax / Télécopieur / ལྷན་སྐྱོད་ / Fax-kut: (867) 360-6369

Toll Free / Sans / ᐱᓕᓴᑦᐸᓄᓂᓗ / Akiittug: 1-855-521-3745

WARNING - This communication, including any attachments contains confidential information intended only for the addressee(s) noted above. Any unauthorized distribution, copying, or disclosure is strictly prohibited. If you have received this by mistake, please notify the sender immediately and delete this message without printing or copying it. Thank you.

AVIS DE CONFIDENTIALITÉ - Ce message, et toute(s) pièce(s) jointe(s) est confidentiel et est à l'usage exclusif du(es) destinataire(s) ci-dessus. Toute autre personne est par la présente avisée qu'il lui est strictement interdit de le diffuser, le distribuer ou le reproduire. Si le destinataire ne peut être joint ou vous est inconnu, veuillez informer l'expéditeur par courrier électronique immédiatement et détruire ce message et toute copie de celui-ci. Merci pour votre collaboration.



 Merci de penser à l'environnement avant d'imprimer ce courriel / Thank you for thinking of the environment before printing this email

----- Forwarded message -----

From: **Eva Paul** <Eva.Paul@aadnc-aadnc.gc.ca>

Date: Mon, Aug 24, 2015 at 12:22 PM

Subject: Fwd: [Licensing] RE: 2BE-NTI0507 Inspection of July 12, 2014

To: "Ene, Cynthia" <cynthia.ene@nwb-oen.ca>

Cc: "Department, Licensing" <licensing@nwb-oen.ca>

Hi Cynthia and nice to make your acquaintance!

I did a quick review of the file, here's my understanding: The collars Mike refers to are of drilling carried out by Cominco prior to Strongbow's tenure. I don't know whether the Cominco drilling was licenced by the NWB, or when it occurred. From what I can gather, the NTI licence was a new licence, not an assignment, and no previous projects are mentioned in the Decision associated with NWB2NTI0305. Therefore, I do not see any legal obligation to Strongbow to remove Cominco's drill collars.

Based on the information provided to me, Strongbow conducted no drilling of their own.

As we discussed on the phone (and as per the attached report), Strongbow's obligation rests in restoring the location of the 2005 fly camp to a pre-disturbed state. However, if Strongbow felt compelled to leave the area better off than they found it and chose to cut the drill collars, then Nunavut would be a little better off, but they are not obliged.

Hope this helps!

Eva

Eva Paul

Water Resources Officer | Agent des ressources en eau
Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada
Nunavut Regional Office | Bureau régional du Nunavut
Building 969, PO Box 2200 | Édifice 969, CP 2200
Iqaluit, NU X0A 0H0

Phone | Tél. : [867-975-4548](tel:867-975-4548)
Cell | Mobile: [867-222-6490](tel:867-222-6490)
Fax | Téléc. : [867-979-6445](tel:867-979-6445)
Eva.Paul@aadnc-aadnc.gc.ca

----- Forwarded message -----

From: **Michael Macmorran** <mmacmorran@northarrowminerals.com>

Date: Thu, Aug 6, 2015 at 2:24 PM

Subject: [Licensing] RE: 2BE-NTI0507 Inspection of July 12, 2014

To: "Licensing Department (licensing@nwb-oen.ca)" <licensing@nwb-oen.ca>, "phyllis.beaulieu@nwb-oen.ca" <phyllis.beaulieu@nwb-oen.ca>

Hi Phyllis,

Sorry, I'm a bit late following up on this. Can you tell me if there has been any resolution as to whether or not Strongbow has to go and remove the old Cominco drill collars Eva noted in her inspection report? Please let me know.

Many thanks!

Mike