



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
FAX: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᓂᓕᓂᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI
OFFICE DES EAUX DU NUNAVUT

NWB FILES: 2BE-ROC0305
2BE-TAK0204

December 10, 2009

Mr. Thomas Pladsen
Chief Restructuring Officer
Benachee Resources Inc.
77 King Street West
Toronto, ON M5K 1P2
Email: thomaspladsen@hotmail.com

Subject: Outstanding Licence Renewals for Polar Property (2BE-ROC0305) and Rockinghorse Property (2BE-TAK0204)

Dear Mr. Pladsen:

The Nunavut Water Board (NWB or Board) received applications for renewal on the above two licences on September 17, 2007. Due to the restructuring of Tahera Diamond Corporation, the files were not fully processed by the NWB at that time and following.

Please be advised that both licences expired prior to receipt of the applications, 2BE-ROC0305 on February 28, 2005 and 2BE-TAK0204 on December 31, 2004. The NWB is writing to the Licensee seeking clarification of the scope of the renewal applications filed in 2007, the sites included in the applications relative to the sites identified in the expired licences, and requesting your views on the status of the renewal applications. All of the information for both files is available on the NWB's ftp site using the username "public" and password "registry", without the quotations.

By copy of this letter, the NWB is requesting that the Water Resources Division of Indian and Northern Affairs Canada in Iqaluit, provide any recent inspection reports generated for these two sites as well as any comments with regard to current status of the sites.

Sincerely,

Original signed by:

Phyllis Beaulieu
Manager of Licencing

Cc: Melissa Joy, INAC Inspections