



P.O. Box 119

GJOA HAVEN, NU X0B 1J0

TEL: (867) 360-6338

Fax: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓚᓕᓕᓂᓪ ᑲᑎᓚᓂᓪ

NUNAVUT WATER BOARD

NUNAVUTIMALIRIYINKATIMAYINGI

File No: NWB2ROC0305

February 10, 2003

Shirley Standafer Pfister

Lands and Government Relations
DeBeers Canada Exploration Inc.
Suite 300, Scotia Centre
5102-50th Avenue
Yellowknife, NT X1A 3S8

SENT VIA E-MAIL:

RE: Spill Contingency Plan Requirements NWB Licence No. NWB2ROC0305

Dear Ms. Standafer Pfister:

The Nunavut Water Board (NWB) has reviewed the Spill Contingency Plan currently on file, and noted several deficiencies. In accordance with Part G, Item 2 of NWB Licence NWB2ROC0305, the Licensee is requested to submit a revised Spill Contingency Plan on or before March 31, 2003. The revised Spill Contingency Plan should include the following:

- (a) Updated contact information for DIAND Water Resources and Environment Canada personnel in Iqaluit;
- (b) A detailed description of the location and contents of Spill Containment kits; and
- (c) A detailed description of additional Spill Response resources, including their location.

If you have any questions or concerns, or if I can be of any further assistance, please do not hesitate to contact me.

Sincerely,

Jim Wall
Technical Advisor
Nunavut Water Board