



Indian and Northern  
Affairs Canada  
[www.ainc.gc.ca](http://www.ainc.gc.ca)

Affaires indiennes  
et du Nord Canada  
[www.ainc.gc.ca](http://www.ainc.gc.ca)

Nunavut Regional Office  
P.O. Box 2200  
Iqaluit, NU, X0A 0H0

Your file - Votre référence  
2BM-ULU0008  
Our file - Notre référence  
IQA-N 9545-1-1ULUG

November 21, 2006

Phyllis Beaulieu  
Licensing Administrator  
Nunavut Water Board  
P.O. Box 119  
Gjoa Haven, NU, X0A 1J0

Email: [licensing@nwb.nunavut.ca](mailto:licensing@nwb.nunavut.ca)

**Re: Wolfden Resources Ltd. - Ulu Gold Project - 2006 Annual Geotechnical Inspection of Selected Structures**

Department of Indian Affairs and Northern Development (DIAND), has reviewed the 2006 Annual Geotechnical Inspection of Selected Structures at the Ulu Mine Project, submitted by Wolfden Resources Ltd. The report was submitted on October 10, 2006 as a requirement of Part D, Item 9 of the Nunavut Water Board water license 2BM-ULU0008 (formerly NWB1ULU0008). The review has been undertaken pursuant to DIAND's mandated responsibilities under the Department of Indian Affairs and Northern Development Act and the Nunavut Water and Nunavut Surface Rights Tribunal Act.

INAC has no major comments on the report. However, the 2006 Annual Report, due by March 31, 2007, will be reviewed to verify comments made in the report on the potential water quality and quantity of the seepage from Portal Laydown (waste rock) Pad and the Ore Pad.

Should you have any questions or comments, please do not hesitate to contact me at (867) 975-4550 or by email at [RogersJi@ainc-ianc.gc.ca](mailto:RogersJi@ainc-ianc.gc.ca).

Sincerely,

*Original Signed By J. Rogers*

Jim Rogers  
Manager, Water Resources

Canada